



report date: 2024-03-29

General information

Make	KIA
Model	PICANTO 1
Colour	White
Year of manufacture	2017
Top speed	100 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 BHP
Max. torque	96 Nm at 3.500 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	64.2 mpg
CO2 emission	101 g/km
CO2 label	B





Internet history


Entry 2

Date	2021-06-23
Pictures	0
Listing price	View report

source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-22
Pictures	28
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-28
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	12
Total items failed	7

MOT #7	2023-06-29 13:33
MOT test number	126414550163
Result	✓ Passed
Next expiry date	2024-06-28
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Daytime running lamp inoperative
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6	2023-06-28 14:54
MOT test number	273220175843
Result	✗ Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Emissions unable to be completed (8.2.1.2 (d))
Advice	Nearside Front Daytime running lamp inoperative
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2022-06-24 14:55**MOT test number** 629636660419**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2022-06-24 14:55**MOT test number** 547710532718**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid both (3.5 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2021-06-28 13:21**MOT test number** 968800923496**Result** ✓ Passed**MOT #2** 2020-09-08 07:02**MOT test number** 976041012798**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** NEARSIDE DOOR MIRROR HOUSING COVER MISSING



MOT #12020-09-07 13:51

MOT test number724350588035

ResultX Failed

- Advice

NEARSIDE DOOR MIRROR HOUSING COVER MISSING
- Fail

Nearside Fuel pipe insecure SECURING BRACKET MISSING (6.1.3 (a) (i))
- Advice

Nearside Rear Nail in tyre
- Fail

Offside Rear Position lamp has a product on the lens or light source which shows white light to the rear DAMAGED (4.2.3 (b) (ii))
- Fail

Brake lever has insufficient reserve travel (1.1.2 (a))



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
28 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	28 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-09-27
Last registration	2023-06-29
Complete history	See info



Registration #1	2017-09-27	19 mi
Registration #2	2020-09-07	27.014 mi
Registration #3	2020-09-08	27.015 mi
Registration #4	2022-06-29	27.017 mi
Registration #5	2022-06-29	27.017 mi
Registration #6	2022-06-29	27.017 mi
Registration #7	2022-06-29	27.017 mi
Registration #8	2022-06-29	27.017 mi
Registration #9	2022-06-29	27.017 mi
Registration #10	2022-06-29	27.017 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	83%
Pedestrian	47%
Safety systems	43%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1595 mm
Height	1485 mm
Length	3595 mm
Kerb weight	1028 kg
Max. allowed weight	1400 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

