



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA SRI NAV CDTi (150)
Colour	Blue
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg



LABEL UNKNOWN

**MOT history**

MOT #11	2020-02-03 10:42
MOT test number	602224830450
Result	✓ Passed
Next expiry date	2021-03-02
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2019-02-13 17:43
MOT test number	126442014358
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear subframe corroded
Advice	All coil springs corroded

MOT #9	2018-02-27 13:39
MOT test number	598329152428
Result	✓ Passed
Advice	Bonnet retaining device slightly deteriorated (8.4.2)

MOT #8	2018-02-23 16:35
MOT test number	395431075823
Result	✗ Failed
Fail	Central Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
Fail	Exhaust emits an excessive level of metered smoke (7.4.B.3a)
Advice	Bonnet retaining device slightly deteriorated (8.4.2)

MOT #7	2017-02-27 08:38
MOT test number	101983784025
Result	✓ Passed

**MOT #6** 2017-02-27 08:38**MOT test number** 505292807767**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2016-03-03 16:20**MOT test number** 468289313183**Result** ✓ Passed**MOT #4** 2015-02-26 12:31**MOT test number** 146437355411**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Nail in nearside rear tyre**MOT #3** 2014-02-27 12:21**MOT test number** 838718154070**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-02-27 10:35**MOT test number** 326748753083**Result** ✓ Passed**MOT #1** 2012-02-18 11:36**MOT test number** 279379442065**Result** ✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KY09FKR
Plate since	2019-09-29
Current registration	 KY09FKR
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-03-01
Last registration	2020-02-03
Complete history	See info



Registration #1	2009-03-01	7 mi
Registration #2	2012-02-18	23.204 mi
Registration #3	2013-02-27	30.646 mi
Registration #4	2014-02-27	37.252 mi
Registration #5	2015-02-26	44.808 mi
Registration #6	2016-03-03	55.722 mi
Registration #7	2016-03-03	55.722 mi
Registration #8	2016-03-03	55.722 mi
Registration #9	2016-03-03	55.722 mi
Registration #10	2016-03-03	55.722 mi
Registration #11	2016-03-03	55.722 mi
Registration #12	2016-03-03	55.722 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1798 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1456 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	17375802