





report date: 2024-03-28

## General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Blue
Year of manufacture	-
Top speed	98 mph
0 - 60 mph	16.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	67 BHP
Max. torque	159 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-28

## **MOT** history

MOT #13	2021-01-27 10:28
MOT test number	636648079812
Result	<b>✓</b> Passed
Next expiry date	2022-01-26

**MOT #12** 2020-01-09 13:47 241787819290 **MOT** test number Result ✓ Passed Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) Offside Rear Nail in tyre Advice Advice Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #11		2019-01-15 13:59
MOT test	number	551742328333
Result		✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	

MOT #10	2017-12-21 14:04
MOT test number	486545386487
Result	<b>✓</b> Passed

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT #9 2016-12-21 13:36

**MOT test number** 512374460792

Result \( \sqrt{Passed} \)

**Advice** Front brake disc modified but not seriously weakened near side and off side (3.5.1n)

MOT #8 2015-12-30 14:04

**MOT test number** 799153768821

Result \( \sqrt{Passed} \)

MOT #7 2015-01-06 12:12

MOT test number 346336805093

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Inner Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2015-01-06 08:51

MOT test number 585676705081

**Result** X Failed

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Inner Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2014-01-06 14:02

**MOT test number** 357606104028

Result 


Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 3/11



report date: 2024-03-28



MOT #3		2012-01-04 11:57
MOT test	number	408494702077
Result		<b>✓</b> Passed
Notice	Front wipers slightly worn	
Notice	Damage to rear bumper	
Notice	O/s/f wing mirror slightly insecure	

MOT #2			2012-01-04 11:57
MOT test	number		198644202491
Result			<b>X</b> Failed
Notice	O/s/f wing mirror	slightly insecure	
Notice	Front wipers slig	htly worn	
Pass wit	th rectification	Offside Rear Stop lamp not working (1.2.1b)	
Notice	Damage to rear	bumper	

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT #1

MOT test number

S85266901077

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
*********	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



FN57CZA report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



FN57CZA report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-04-24
Last registration	2021-01-27
Complete history	See info



Registration #1	2008-04-24	16 mi
Registration #2	2011-01-06	17.374 mi
Registration #3	2012-01-04	22.691 mi
Registration #4	2013-01-04	27.805 mi
Registration #5	2014-01-06	36.830 mi
Registration #6	2015-01-06	48.615 mi
Registration #7	2015-01-06	48.615 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		10.777 au

More info >

CarCheck.co.uk page 10/11



FN57CZA report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1237 kg
Max. allowed weight	1640 kg

## Additional information

Fuel tank capacity	43 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/

Number of axles 2

**Engine number** 7P39375