



PEUGEOT

EK54RNY

report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 S
Colour	Silver
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	120 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-19
Pictures	3
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #19	2022-10-24 11:33
MOT test number	255989404802
Result	✓ Passed
Next expiry date	2023-11-18
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))
Advice	Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Nail in tyre
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #18	2021-11-19 09:35
MOT test number	540093088618
Result	✓ Passed
Advice	Oil leak, but not excessive gearbox oil (8.4.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17	2021-11-12 14:41
MOT test number	183632465471
Result	✗ Failed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive gearbox oil (8.4.1 (a) (i))
Fail	Offside Front Tyre has a tear, caused by separation or partial failure of its structure 175 65 14 (5.2.3 (d) (ii))

**MOT #16** 2020-10-16 11:24**MOT test number** 308967947281**Result** ✓ Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #15 2020-10-16 11:24**MOT test number** 611481791408**Result** ✗ Failed

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Pass with rectification Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #14 2019-10-02 11:52**MOT test number** 989924281248**Result** ✓ Passed**MOT #13** 2018-10-15 09:15**MOT test number** 985307220994**Result** ✓ Passed**MOT #12** 2017-10-13 12:21**MOT test number** 431263210635**Result** ✓ Passed

**MOT #11** 2016-10-14 10:58**MOT test number** 365300579635**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in an outer ball joint (2.5.B.2a)**MOT #10** 2015-10-09 10:27**MOT test number** 228190503525**Result** ✓ Passed**MOT #9** 2014-09-26 11:23**MOT test number** 128949564219**Result** ✓ Passed**MOT #8** 2013-09-26 15:29**MOT test number** 138229963214**Result** ✓ Passed**MOT #7** 2012-09-28 08:46**MOT test number** 278352972214**Result** ✓ Passed**Notice** Airbag light on**MOT #6** 2011-09-30 12:07**MOT test number** 435233071246**Result** ✓ Passed

**MOT #5** 2010-09-17 14:59**MOT test number** 544560760289**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #4** 2009-09-18 09:56**MOT test number** 430321969238**Result** ✓ Passed**MOT #3** 2009-09-18 09:39**MOT test number** 614211869275**Result** ✗ Failed**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**MOT #2** 2008-09-26 11:28**MOT test number** 232420878224**Result** ✓ Passed**MOT #1** 2007-09-14 11:02**MOT test number** 291957657234**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	EK54RNY
Plate since	2019-03-28
Current registration	EK54RNY
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-09-30
Last registration	2022-10-24
Complete history	See info



Registration #1	2004-09-30	12 mi
Registration #2	2007-09-14	25.345 mi
Registration #3	2008-09-26	33.234 mi
Registration #4	2009-09-18	38.069 mi
Registration #5	2009-09-18	38.069 mi
Registration #6	2010-09-17	45.571 mi
Registration #7	2011-09-30	48.631 mi
Registration #8	2012-09-28	50.220 mi
Registration #9	2013-09-26	51.243 mi
Registration #10	2014-09-26	52.367 mi
Registration #11	2015-10-09	54.379 mi
Registration #12	2016-09-28	55.377 mi
Registration #13	2017-09-28	56.377 mi
Registration #14	2018-09-28	57.377 mi
Registration #15	2019-09-28	58.377 mi
Registration #16	2020-09-28	59.377 mi
Registration #17	2021-09-28	60.377 mi
Registration #18	2022-09-28	61.377 mi
Registration #19	2023-09-28	62.377 mi
Registration #20	2024-09-28	63.377 mi
Registration #21	2025-09-28	64.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

FSR94900767