



AF57KBP

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO E (55BHP)
Colour	Blue
Year of manufacture	2007
Top speed	94 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	138 g/km
CO2 label	E





MOT history

MOT expiry date	2021-01-07
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #11	2020-01-08 11:48
MOT test number	629554449062
Result	✓ Passed
Next expiry date	2021-01-07

MOT #10	2020-01-08 10:56
MOT test number	519432364621
Result	✗ Failed
Fail	Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))

MOT #9	2018-12-13 15:37
MOT test number	688506370438
Result	✓ Passed
Advice	Offside rear tyre perished.
Advice	Exhaust flex joint in poor condition.

MOT #8	2017-12-05 09:38
MOT test number	724560270108
Result	✓ Passed
Advice	Offside Rear Tyre worn on outer sidewall
Advice	Nearside Rear Tyre worn on outer sidewall



MOT #7	2016-11-29 16:07
MOT test number	435548965719
Result	✓ Passed
Advice	Rear tyres cracking and deteriorated.

MOT #6	2015-11-25 11:07
MOT test number	980627701501
Result	✓ Passed
Advice	Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #5	2014-11-25 14:01
MOT test number	209189224311
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #4	2013-11-01 10:40
MOT test number	888465103326
Result	✓ Passed

MOT #3	2012-11-02 12:02
MOT test number	288207002326
Result	✓ Passed
Notice	Both rear tyres cracking in tread

MOT #2	2011-10-27 12:16
MOT test number	768310301386
Result	✓ Passed



MOT #1	2010-11-25 12:20
MOT test number	412539720344
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
26 November 2020

X

MOT

Expired:
7 January 2021

Tax status	Expired at 26 November 2020
Days left	1250 days too late
MOT expiry date	7 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 AF57KBP
Plate since	2024-03-28
Current registration	 AF57KBP
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2007-10-26
Last registration	2020-01-08
Complete history	See info



Registration #1	2007-10-26	15 mi
Registration #2	2010-11-25	14.304 mi
Registration #3	2011-10-27	15.901 mi
Registration #4	2012-11-02	17.551 mi
Registration #5	2013-11-01	19.062 mi
Registration #6	2014-11-25	20.697 mi
Registration #7	2015-11-25	21.337 mi
Registration #8	2016-11-25	21.977 mi
Registration #9	2017-11-25	22.617 mi
Registration #10	2018-11-25	23.257 mi
Registration #11	2019-11-25	23.897 mi
Registration #12	2020-01-08	24.537 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1186 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BMD194531