



report date: 2024-03-29

General information

Make	VOLVO
Model	V40 T2 R-DESIGN EDITION
Colour	Grey
Year of manufacture	2019
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	121 BHP
Max. torque	220 Nm at 1.800 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption combined	38.2 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 2

Date	2022-07-06
Pictures	1
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

Entry 1

Date	2022-07-02
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-10
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #4	2023-08-11 14:12
MOT test number	504556261594
Result	✓ Passed
Next expiry date	2024-08-10

MOT #3	2022-08-04 15:14
MOT test number	707099211651
Result	✓ Passed

**Advice**    Nearside Front Tyre slightly damaged/cracking or perishing outer wall cracked (5.2.3 (d) (ii))

**MOT #2** 2022-08-03 09:19**MOT test number** 614366899424**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracked (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing outer wall cracked (5.2.3 (d) (ii))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing outer wall cracked (5.2.3 (d) (ii))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracked (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MOT #1** 2022-01-26 11:15**MOT test number** 662138953441**Result** ✓ Passed**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**Advice** Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
10 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	10 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>First licence fee (12 months)</b>	£ 210,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>PF68SHJ</b>
Plate since	2024-03-29
Current registration	<b>PF68SHJ</b>
Plate since	2024-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-02-04
Last registration	2023-08-11
Complete history	<a href="#">See info</a>



Registration #1	2019-02-04	21 mi
Registration #2	2022-01-26	21,476 mi
Registration #3	2023-08-11	21,500 mi
Registration #4	2023-08-11	21,500 mi
Registration #5	2023-08-11	21,500 mi
Registration #6	2023-08-11	21,500 mi
Registration #7	2023-08-11	21,500 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1857 mm
Height	1439 mm
Length	4369 mm
Max. allowed weight	1965 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	2988519