





report date: 2024-03-29

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Silver
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2022-07-05


Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-03-13
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	13
Total items failed	0

MOT #4	2024-03-14 14:47
MOT test number	849907668960
Result	✓ Passed
Next expiry date	2025-03-13
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))

MOT #3			2024-03-13 15:45
MOT test r	numbe	er	204676443334
Result			× Failed
MAJOR	Offsid	le Front Tyre fouling a part of the vehicle (5.2.3 (f))	
MAJOR	Offsio	le Front Coil spring fractured or broken (5.3.1 (b) (i))	
DANGER	ous	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGER(ous	Offside Front Tyre has a tear, caused by separation or partial failure of	its structure (5.2.3
MAJOR (ii))	Offsid	le Rear Registration plate lamp inoperative in the case of a single lamp o	or all lamps (4.7.1 (b)
DANGER	ous	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e	2))
Advice	Nears	side Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front	Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Nail in tyre

MOT #1

MOT test number

Result

Advice Front Brake discs in a poor state

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	13 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report if	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2008-07-28
Last registration	2024-03-14
Complete history	See info



Registration #1	2008-07-28	18 mi
Registration #2	2021-12-17	89.867 mi
Registration #3		11.777 es
Registration #4		71.777 es
Registration #5		11.777 no
Registration #6		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number 8A48618