



report date: 2024-03-29

General information

Make	NISSAN
Model	PATHFINDER DCI T-SPEC
Colour	Grey
Year of manufacture	2006
Top speed	109 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	172 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	37.2 mpg
Consumption combined	31.4 mpg
CO2 emission	238 g/km
CO2 label	L





Internet history

Entry 2

Date	2021-09-05
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-09-03
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-27
MOT pass rate	60 %
MOT passed	15
Failed MOT tests	10
Total advice items	109
Total items failed	26

MOT #25	2023-06-28 10:54
---------	------------------

MOT test number	116061398704
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-06-27
------------------	------------

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** One wheel nut different size on all four wheels.
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Rear Fuel filler pipe corroded.
- Advice** Front Service brake binding but not excessively s (1.2.1 (f))
- Advice** Spare tyre cord exposed.

**MOT #24**

2023-06-08 10:16

**MOT test number**

137823076782

**Result****✗ Failed****Fail** Offside Rear Seat belt not functioning as intended Rear. (7.1.2 (c))**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Rear Fuel filler pipe corroded.**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Spare tyre cord exposed.**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Service brake binding but not excessively s (1.2.1 (f))**Fail** Nearside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** One wheel nut different size on all four wheels.**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #23**

2022-05-06 13:53

**MOT test number**

637657972617

**Result**

✓ Passed

**Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**Advice** Offside Rear One wheel nut incorrectly fitted

**Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #22**

2022-04-21 10:17

**MOT test number**

804303918002

**Result**

✗ Failed

**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Fail** Offside Rear Vehicle structure has excessive corrosion which adversely affects braking or steering Within 30cm of suspension components (6.1.1 (c) (ii))

**Advice** Offside Rear One wheel nut incorrectly fitted

**Fail** Offside Front Headlamp aim not tested (4.1.2 (b))

**Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Fail** Offside Rear Seat belt webbing significantly weakened (7.1.2 (b) (ii))

**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**Advice** Rear Not raised due to corrosion on chassis

**MOT #21**

2021-04-07 11:09

**MOT test number**

108314438235

**Result**

✓ Passed

- Advice** Seat belt webbing slightly damaged or frayed Both 3rd row seat belts (7.1.2 (b) (ii))
- Advice** Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement Both forward arms (5.3.4 (a) (i))
- Advice** Fuel Pipe/s corroded Fuel filler pipes
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement Radius arm (5.3.4 (a) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced Complete chassis corroded (6.1.1 (c) (i))

**MOT #20**

2021-04-07 08:18

**MOT test number**

238557544935

**Result**

✗ Failed

- Advice** Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement Both forward arms (5.3.4 (a) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced Complete chassis corroded (6.1.1 (c) (i))
- Advice** Seat belt webbing slightly damaged or frayed Both 3rd row seat belts (7.1.2 (b) (ii))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement Radius arm (5.3.4 (a) (i))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Fuel Pipe/s corroded Fuel filler pipes

**MOT #19**

2020-04-08 09:20

**MOT test number**

584533214610

**Result**

✓ Passed

- Advice** Fuel Pipe/s corroded Fuel filler pipes
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Forward inner bush (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Both bushes (5.3.4 (a) (i))
- Advice** Rear Seat belt webbing slightly damaged or frayed Both 3rd row seat belts (7.1.2 (b) (ii))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Forward inner bush (5.3.4 (a) (i))

**MOT #18**

2020-04-07 13:45

**MOT test number**

380656882321

**Result**

✗ Failed

- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Rear Seat belt webbing slightly damaged or frayed Both 3rd row seat belts (7.1.2 (b) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Both bushes (5.3.4 (a) (i))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Forward inner bush (5.3.4 (a) (i))
- Advice** Fuel Pipe/s corroded Fuel filler pipes
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Forward inner bush (5.3.4 (a) (i))

**MOT #17**

2019-04-08 12:19

**MOT test number**

422123267746

**Result**

✓ Passed

- Advice** Fuel Pipe/s corroded Fuel filler pipes
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #16**

2019-04-08 10:41

**MOT test number**

549011199324

**Result**

✗ Failed

- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush (5.3.4 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Fuel Pipe/s corroded Fuel filler pipes
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Offside Rear Position lamp not working (4.2.1 (a))
- Fail** Front Tyre not fitted in accordance with side wall instructions Both (5.2.3 (i))



**MOT #15**

2018-04-04 10:46

**MOT test number**

674488776450

**Result**

✓ Passed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear bush (2.4.G.2)

**Advice** Vehicle structure has slight corrosion (6.1.A.1)

**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)

**MOT #14**

2018-04-04 07:41

**MOT test number**

326107961236

**Result**

✗ Failed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear bush (2.4.G.2)

**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)

**Advice** Vehicle structure has slight corrosion (6.1.A.1)

**Fail** Nearside Rear coil spring broken (2.4.C.1a)

**MOT #13**

2017-04-06 06:31

**MOT test number**

576396104344

**Result**

✓ Passed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear bush (2.4.G.2)

**Advice** Offside Front Drivers seat adjustment forward and back doesn't work.



MOT #12	2017-04-05 07:30
MOT test number	642433728126
Result	✗ Failed
Advice	Offside Front Drivers seat adjustment forward and back doesn't work.
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear bush (2.4.G.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #11	2016-04-07 10:29
MOT test number	701232041400
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Vehicle structure has slight corrosion (6.1.A.1)
Advice	Front Inner brake disc worn, pitted or scored, but not seriously weakened face (3.5.1i)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Parking brake lever has little reserve travel (3.1.6b)

**MOT #10** 2016-04-07 10:29**MOT test number** 598100157550**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working side (1.1.A.3b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Vehicle structure has slight corrosion (6.1.A.1)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened face (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #9** 2015-04-07 14:31**MOT test number** 207577395023**Result** ✓ Passed**Advice** Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-03-20 13:39**MOT test number** 357469674018**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2014-03-17 13:35**MOT test number** 146826774036**Result** ✗ Failed**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #6** 2013-03-26 12:54**MOT test number** 169245083468**Result** ✓ Passed**Notice** Slight play to both front suspension lower ball joints**MOT #5** 2012-03-28 12:50**MOT test number** 167888882060**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-03-31 15:26**MOT test number** 189040991087**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #3** 2011-03-28 11:26**MOT test number** 669837081077**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear coil spring fractured (2.4.C.1a)
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Rear fog lamp not working (1.3.2b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #2** 2010-03-24 12:21**MOT test number** 273233080079**Result** ✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #1** 2009-03-06 14:01**MOT test number** 773935269027**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
27 June 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	27 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2006-04-01
Last registration	2023-06-28
Complete history	<a href="#">See info</a>



Registration #1	2006-04-01	23 mi
Registration #2	2009-03-06	38.445 mi
Registration #3	2010-03-24	56.618 mi
Registration #4	2011-03-28	70.567 mi
Registration #5	2011-03-31	70.661 mi
Registration #6	2012-03-28	76.729 mi
Registration #7	2013-03-26	86.714 mi
Registration #8	2014-03-17	96.119 mi
Registration #9	2014-03-20	96.245 mi
Registration #10	2015-04-07	101.009 mi
Registration #11	2016-04-07	106.902 mi
Registration #12	2016-04-07	106.902 mi
Registration #13	2017-04-05	113.358 mi
Registration #14	2017-04-06	113.358 mi
Registration #15	2018-04-05	113.358 mi
Registration #16	2018-04-05	113.358 mi
Registration #17	2018-04-05	113.358 mi
Registration #18	2018-04-05	113.358 mi
Registration #19	2018-04-05	113.358 mi
Registration #20	2018-04-05	113.358 mi
Registration #21	2018-04-05	113.358 mi
Registration #22	2018-04-05	113.358 mi
Registration #23	2018-04-05	113.358 mi
Registration #24	2018-04-05	113.358 mi
Registration #25	2018-04-05	113.358 mi
Registration #26	2018-04-05	113.358 mi

Registration #27	2025-05-20	25,000,000
Registration #28	2025-05-20	25,000,000

[More info >](#)



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1850 mm
Height	1783 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2267 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	673548