



HJ6IVBD

report date: 2024-03-29

General information

Make	MAZDA
Model	CX-7 D SPORT TECH
Colour	Silver
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.184 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J








Internet history

Entry 1

Date	2022-01-07
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-22
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	24
Total items failed	7

MOT #13	2023-11-17 08:58
MOT test number	871310563455
Result	✓ Passed
Next expiry date	2024-11-22

MOT #12	2023-11-17 08:58
MOT test number	763175348215
Result	✗ Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Pass with rectification	Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #11	2022-11-21 10:12
MOT test number	241829866426
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10** 2021-11-23 11:03**MOT test number** 151602600676**Result** ✓ Passed**Advice** Reserve travel at handbrake lever at a minimum**Advice** Rear Tyre worn close to legal limit/worn on edge both rears inner edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view small chip / crack centre screen lower edge (3.2 (a) (i))**MOT #9** 2021-11-22 12:11**MOT test number** 997690394989**Result** ✗ Failed**Minor** Windscreen damaged but not adversely affecting driver's view small chip / crack centre screen lower edge (3.2 (a) (i))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Reserve travel at handbrake lever at a minimum**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Rear Tyre worn close to legal limit/worn on edge both rears inner edge (5.2.3 (e))**MOT #8** 2020-11-10 10:24**MOT test number** 519886462157**Result** ✓ Passed**MOT #7** 2019-10-15 08:11**MOT test number** 540876427924**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2018-11-05 16:53**MOT test number** 706063537991**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened o/s and n/s (1.1.14 (a) (ii))**Advice** Suspension component corroded but not seriously weakened Front and rear (5.3.3 (b) (i))**Advice** Park brake lever has little reserve travel**MOT #5** 2018-11-05 12:28**MOT test number** 540601049953**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened o/s and n/s (1.1.14 (a) (ii))**Advice** Suspension component corroded but not seriously weakened Front and rear (5.3.3 (b) (i))**Fail** Front Tyre tread depth below requirements of 1.6mm o/s and n/s 235/55/19 (5.2.3 (e))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #4** 2017-10-27 14:54**MOT test number** 827357788081**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2016-10-31 15:50**MOT test number** 328904349532**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #2	2015-10-19 16:31
MOT test number	902726693015
Result	✓ Passed

MOT #1	2014-08-27 08:47
MOT test number	619549534286
Result	✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
22 November 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	22 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-14
Last registration	2023-11-17
Complete history	See info



Registration #1	2011-09-14	28 mi
Registration #2	2014-08-27	35.934 mi
Registration #3	2015-10-19	50.792 mi
Registration #4	2016-10-31	59.901 mi
Registration #5	2017-10-27	68.298 mi
Registration #6	2018-11-05	77.550 mi
Registration #7	2018-11-05	77.550 mi
Registration #8	2019-10-15	90.868 mi
Registration #9	2019-10-15	90.868 mi
Registration #10	2019-10-15	90.868 mi
Registration #11	2019-10-15	90.868 mi
Registration #12	2019-10-15	90.868 mi
Registration #13	2019-10-15	90.868 mi
Registration #14	2019-10-15	90.868 mi
Registration #15	2019-10-15	90.868 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	76%
Children	79%
Pedestrian	43%
Safety systems	71%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4700 mm
Wheel base	2750 mm
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R210287355