



TOYOTA

RE58YSA


report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO VVT-I SR
Colour	Silver
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 2


Date	2022-01-28
Pictures	10
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-27
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-04
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	45
Total items failed	11

MOT #21	2023-08-01 12:06
---------	------------------

MOT test number	954215380605
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-08-04
------------------	------------

- Advice** Oil leak, but not excessive Transmission (8.4.1 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Drive belt worn, but not excessively (6.1.7 (c) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #20**

2023-08-01 08:26

MOT test number

127774673059

Result**✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Oil leak, but not excessive Transmission (8.4.1 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Front Registration plate inscription missing (0.1 (b))**Advice** Drive belt worn, but not excessively (6.1.7 (c) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #19**

2022-08-02 08:26

MOT test number

558341289061

Result**✓ Passed****Advice** Drive belt worn, but not excessively (6.1.7 (c) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Advice** Registration plate deteriorated but not likely to be misread Both (0.1 (b))**Advice** Coolant level low**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #18**

2022-08-02 08:26

MOT test number

154630631854

Result**✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Registration plate deteriorated but not likely to be misread Both (0.1 (b))**Advice** Drive belt worn, but not excessively (6.1.7 (c) (i))**Advice** Coolant level low**MOT #17**

2021-07-26 08:27

MOT test number

447048327050

Result**✓ Passed****Advice** Registration plate deteriorated but not likely to be misread Front & Rear (0.1 (b))**MOT #16**

2021-07-26 08:27

MOT test number

313658630599

Result**✗ Failed****Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Registration plate deteriorated but not likely to be misread Front & Rear (0.1 (b))**MOT #15**

2020-08-05 13:43

MOT test number

211914169718

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2020-08-05 13:43**MOT test number** 256599602363**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2019-07-24 10:23**MOT test number** 158593101175**Result** ✓ Passed**MOT #12** 2019-07-24 10:12**MOT test number** 941016427660**Result** ✗ Failed**Fail** Front Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))**MOT #11** 2018-07-11 09:20**MOT test number** 970917196467**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #10** 2017-07-18 14:55**MOT test number** 746748263678**Result** ✓ Passed**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2017-07-18 10:27**MOT test number** 129168870938**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #8** 2016-07-19 11:11**MOT test number** 563087965052**Result** ✓ Passed**MOT #7** 2015-07-21 09:56**MOT test number** 368082405255**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #6** 2014-07-15 09:15**MOT test number** 856646594168**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #5** 2014-07-15 09:15**MOT test number** 217636594191**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #4** 2013-07-24 09:15**MOT test number** 349495903493**Result** ✓ Passed**MOT #3** 2012-07-21 11:21**MOT test number** 338083502484**Result** ✓ Passed**MOT #2** 2011-07-30 12:18**MOT test number** 315721511499**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-07-30 12:18**MOT test number** 986821511209**Result** ✗ Failed**Pass with rectification** Headlamp aim too low (1.8)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
4 August 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	4 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	RE58YSA
Plate since	2024-03-29
Current registration	RE58YSA
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-09-30
Last registration	2023-08-01
Complete history	See info



Registration #1	2008-09-30	17 mi
Registration #2	2011-07-30	22.540 mi
Registration #3	2012-07-21	31.134 mi
Registration #4	2013-07-24	40.378 mi
Registration #5	2014-07-15	47.548 mi
Registration #6	2015-07-21	55.468 mi
Registration #7	2016-07-19	63.035 mi
Registration #8	2017-07-18	71.535 mi
Registration #9	2017-07-18	71.535 mi
Registration #10	2018-07-11	78.242 mi
Registration #11	2019-07-24	83.565 mi
Registration #12	2020-05-20	85.000 mi
Registration #13	2020-05-20	85.000 mi
Registration #14	2020-05-20	85.000 mi
Registration #15	2020-05-20	85.000 mi
Registration #16	2020-05-20	85.000 mi
Registration #17	2020-05-20	85.000 mi
Registration #18	2020-05-20	85.000 mi
Registration #19	2020-05-20	85.000 mi
Registration #20	2020-05-20	85.000 mi
Registration #21	2020-05-20	85.000 mi
Registration #22	2023-08-01	85.000 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1ZZV035065