





report date: 2024-03-29

#### General information

Make	CLIDADLI
Make	SUBARU
Model	XV I SE PREMIUM
Colour	White
Year of manufacture	2016
Top speed	116 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed CVT

## Engine & fuel consumption

Power	150 BHP	
Max. torque	196 Nm at 4.200 rpm	
Engine capacity	1.998 сс	
Cylinders	4	
Fuel type	Petrol	
Consumption city	33.2 mpg	
Consumption extra urban	51.4 mpg	
Consumption combined	43.5 mpg	
CO2 emission	151 g/km	
CO2 label	G	



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

## Entry 2


Date 2021-07-10

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-09

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



YT16OZP report date: 2024-03-29

MOT history

MOT expiry date	2025-02-12
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	18
Total items failed	3

MOT #8		2024-02-09 17:04
MOT test	number	477908077481
Result		✓ Passed
Next expi	ry date	2025-02-12
Advice	O/S/F tyre perished	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (	ii))

MOT #7	2024-02-01 16:17	
MOT test number	457540421734	
Result	<b>×</b> Failed	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.	14 (a) (ii))	
Fail Electronic power steering warning lamp indicates a system malfunction (2.6 (a))		
Advice O/S/F tyre perished		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Fail Rear Stop lamp(s) not working (4.3.1 (a) (ii))		
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		

CarCheck.co.uk page 3/12



report date: 2024-03-29

**MOT #6** 2023-02-13 11:16 **MOT** test number 883716604302 Result ✓ Passed **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

Result

Advice (d) (ii))

Advice
Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice
(ii))

Offside Front Tyre slightly damaged/cracking or perishing cracked and perished in tread (5.2.3 (d) (ii))

MOT #4

MOT test number

Result

2021-02-11 10:12

331583621488

✓ Passed

MOT #3

MOT test number

Result

Pass with rectification

Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/12



YT16OZP report date: 2024-03-29

MOT #2	2020-02-11 09:26
MOT test number	295501972086
Result	<b>✓</b> Passed
MOT #1	2019-02-06 11:04
MOT test number	659844044558
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



YT16OZP report date: 2024-03-29

# Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	12 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this SUBARU. See if, where and when this SUBARU had damage and the car repair costs. We also check if this SUBARU was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra SUBARU salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



YT160ZP report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this SUBARU in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this SUBARU? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
********	
***************************************	
************	
********	
***************************************	
THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this SUBARU had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info

CarCheck.co.uk page 9/12



YT16OZP report date: 2024-03-29

#### Finance check

Check if this SUBARU is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUBARU has been settled.

If not, and you buy this SUBARU then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUBARU is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >


CarCheck.co.uk page 10/12



YT160ZP report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-01
Last registration	2024-02-09
Complete history	See info



Registration #1	2016-03-01	7 mi
Registration #2	2019-02-06	18.898 mi
Registration #3	2020-02-11	27.588 mi
Registration #4	2021-02-11	31.962 mi
Registration #5	2021-02-11	31.962 mi
Registration #6		0.00 44
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		D.777 es
Registration #11		10.377 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Safety ratings

NCAP rating	****
Adult	86%
Children	90%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



# Dimensions & weight

Width	1780 mm
Height	1615 mm
Length	4450 mm
Wheel base	2635 mm
Kerb weight	1390 kg
Max. allowed weight	1940 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	106075

CarCheck.co.uk page 12/12