



PEUGEOT

FE06HZN

report date: 2024-03-28

General information

Make	PEUGEOT
Model	407 HDI SE
Colour	Silver
Year of manufacture	-
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN



Internet history

Entry 2


Date	2021-07-27
Pictures	21
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-26
Pictures	21
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #20	2022-10-13 13:17
MOT test number	903471003715
Result	✓ Passed
Next expiry date	2023-10-12
Advice	Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))
Advice	Nearside Front Headlamp has a product on the lens but not seriously reducing light output Slightly Dim (4.1.4 (b))

MOT #19	2022-10-11 12:44
MOT test number	747216136078
Result	✗ Failed
Advice	Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Nearside Front Headlamp has a product on the lens but not seriously reducing light output Slightly Dim (4.1.4 (b))
Fail	Nearside Front Headlamp aim too low (4.1.2 (a))

MOT #18	2021-10-12 12:00
MOT test number	787974412885
Result	✓ Passed

MOT #17	2021-01-08 16:57
MOT test number	654124922317
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16** 2020-01-07 11:58**MOT test number** 921978527855**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** Towball/hitch not fitted at time of test**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**MOT #15** 2019-01-21 14:58**MOT test number** 366994442704**Result** ✓ Passed**MOT #14** 2019-01-21 11:52**MOT test number** 170919698402**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #13** 2018-01-03 09:31**MOT test number** 589220844295**Result** ✓ Passed**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #12** 2017-01-26 09:07**MOT test number** 220009038628**Result** ✓ Passed**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #11** 2016-02-01 11:36**MOT test number** 193134551963**Result** ✓ Passed**Advice** Nearside Rear Inner Brake pad(s) wearing thin is very low and outer is low (3.5.1g)**MOT #10** 2015-02-02 12:00**MOT test number** 257563635040**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Outer Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-02-05 12:35**MOT test number** 819916034045**Result** ✓ Passed**Notice** Both front tyres on 2-3mm 215/55R17**MOT #8** 2013-02-20 10:50**MOT test number** 436671353035**Result** ✓ Passed**Notice** O/s/r tyre on 3.mm**MOT #7** 2013-02-19 14:15**MOT test number** 276320153090**Result** ✗ Failed**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** O/s/r tyre on 3.mm

**MOT #6** 2012-02-16 13:03**MOT test number** 957997842099**Result** ✓ Passed**MOT #5** 2012-02-16 12:46**MOT test number** 685917842088**Result** ✗ Failed**Fail** Offside Front Headlamp aim too high (1.8)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2011-02-04 09:39**MOT test number** 129915131097**Result** ✓ Passed**MOT #3** 2010-02-15 08:51**MOT test number** 723816740062**Result** ✓ Passed**MOT #2** 2009-03-02 15:59**MOT test number** 173241269410**Result** ✓ Passed**MOT #1** 2009-02-23 09:02**MOT test number** 371044059090**Result** ✗ Failed**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	FE06HZN
Plate since	2019-09-28
Current registration	FE06HZN
Plate since	2019-09-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	23
First mileage registration	2006-03-01
Last registration	2022-10-13
Complete history	See info



Registration #1	2006-03-01	27 mi
Registration #2	2009-02-23	20.938 mi
Registration #3	2009-03-02	21.169 mi
Registration #4	2010-02-15	33.450 mi
Registration #5	2011-02-04	40.269 mi
Registration #6	2012-02-16	44.092 mi
Registration #7	2012-02-16	44.092 mi
Registration #8	2013-02-19	47.388 mi
Registration #9	2013-02-20	47.423 mi
Registration #10	2014-02-05	50.696 mi
Registration #11	2015-02-02	54.196 mi
Registration #12	2016-02-01	57.848 mi
Registration #13	2016-02-01	57.848 mi
Registration #14	2016-02-01	57.848 mi
Registration #15	2016-02-01	57.848 mi
Registration #16	2016-02-01	57.848 mi
Registration #17	2016-02-01	57.848 mi
Registration #18	2016-02-01	57.848 mi
Registration #19	2016-02-01	57.848 mi
Registration #20	2016-02-01	57.848 mi
Registration #21	2016-02-01	57.848 mi
Registration #22	2016-02-01	57.848 mi
Registration #23	2016-02-01	57.848 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1811 mm
Height	1455 mm
Length	4676 mm
Wheel base	2725 mm
Kerb weight	1580 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	DYTJ4054568