



**E005GDE**

report date: 2024-03-28

General information

Make	FORD
Model	FUSION FUSION 2
Colour	Silver
Year of manufacture	-
Top speed	111 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	99 BHP
Max. torque	146 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.7 mpg



LABEL UNKNOWN



## Internet history

### Entry 1

Date	2021-05-26
Pictures	7
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #16</b>	2022-04-16 15:03
<b>MOT test number</b>	444666488800
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-04-15
<b>Advice</b>	Tyre slightly damaged/cracking or perishing both rear tyres outer sidewall (5.2.3 (d) (ii))
<b>Minor</b>	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

<b>MOT #15</b>	2021-03-03 12:17
<b>MOT test number</b>	814684687204
<b>Result</b>	✓ Passed
<b>Minor</b>	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

<b>MOT #14</b>	2020-03-10 16:16
<b>MOT test number</b>	456425450092
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Nail in tyre
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

<b>MOT #13</b>	2019-03-04 10:14
<b>MOT test number</b>	298976341298
<b>Result</b>	✓ Passed

<b>MOT #12</b>	2018-03-12 11:27
<b>MOT test number</b>	304204025804
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
<b>Advice</b>	Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #11** 2017-03-27 13:56**MOT test number** 454642827310**Result** ✓ Passed**MOT #10** 2016-04-04 13:46**MOT test number** 135416567950**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit 1.6mm (4.1.E.1)
- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside Front Tyre worn close to the legal limit 1.6mm (4.1.E.1)
- Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #9** 2015-04-13 15:36**MOT test number** 908413705119**Result** ✓ Passed

- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #8** 2014-04-16 16:00**MOT test number** 339106704157**Result** ✓ Passed**MOT #7** 2013-04-09 16:07**MOT test number** 626339393033**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2012-04-02 15:08**MOT test number** 539903092053**Result** ✓ Passed



<b>MOT #5</b>	2011-04-11 13:59
---------------	------------------

<b>MOT test number</b>	668921901183
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2011-04-11 13:59
---------------	------------------

<b>MOT test number</b>	767971201156
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Fuel cap/sealing device sealing washer missing (7.2.4c)
--------------------------------	---

<b>MOT #3</b>	2010-04-19 14:50
---------------	------------------

<b>MOT test number</b>	690139400167
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2009-04-24 17:10
---------------	------------------

<b>MOT test number</b>	782284719121
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2008-04-10 16:49
---------------	------------------

<b>MOT test number</b>	982211608188
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2005-04-28
Last registration	2022-04-16
Complete history	<a href="#">See info</a>



Registration #1	2005-04-28	22 mi
Registration #2	2008-04-10	8.260 mi
Registration #3	2009-04-24	11.650 mi
Registration #4	2010-04-19	14.136 mi
Registration #5	2011-04-11	17.641 mi
Registration #6	2012-04-02	20.470 mi
Registration #7	2013-04-09	25.454 mi
Registration #8	2014-04-16	29.754 mi
Registration #9	2015-04-13	33.932 mi
Registration #10	2016-04-10	38.110 mi
Registration #11	2017-04-07	42.288 mi
Registration #12	2018-04-04	46.466 mi
Registration #13	2019-04-01	50.644 mi
Registration #14	2020-03-28	54.822 mi
Registration #15	2021-03-25	58.999 mi
Registration #16	2022-04-16	63.177 mi
Registration #17	2023-04-13	67.355 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	5P21641