





report date: 2024-03-29

General information

| Make | VOLKSWAGEN |
|---------------------|-------------------|
| Model | GOLF SE TDI DSG |
| Colour | Black |
| Year of manufacture | 2010 |
| Top speed | 117 mph |
| 0 - 60 mph | 11.3 seconds |
| Gearbox | 7 speed Semi Auto |

Engine & fuel consumption

| Power | 105 BHP |
|-------------------------|---------------------|
| Max. torque | 250 Nm at 1.500 rpm |
| Engine capacity | 1.600 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 62.8 mpg |
| CO2 emission | 123 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-02-06

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2023-06-12 |
|--------------------|------------|
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 17 |
| Total items failed | 3 |

| MOT #11 | | 2022-06-13 10:48 |
|---|--|----------------------------|
| MOT test | number | 103152179908 |
| Result | | ✓ Passed |
| Next exp | iry date | 2023-06-12 |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice (i)) | Offside Front Suspension arm pin or bush worn but not resulting in exce | essive movement (5.3.4 (a) |
| Minor | Nearside Front Anti-roll bar linkage ball joint dust cover severely deterior | rated (5.3.4 (b) (i)) |
| Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) | | |
| Minor | Nearside Front Drive shaft joint constant velocity boot severely deteriora | ited (6.1.7 (g) (i)) |
| Minor | Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorate | ted (5.3.4 (b) (i)) |

| MOT #10 | 2020-12-24 17:30 |
|--------------------------|------------------|
| MOT test number | 773734217498 |
| Result | ✓ Passed |
| Advice Under tray fitted | |

| MOT #9 | 2019-06-03 14:21 |
|---|------------------|
| MOT test number | 867770345074 |
| Result | ✓ Passed |
| Advice Full length under trays fitted obscuring underside from inspection | |

CarCheck.co.uk page 3/12



 MOT #8
 2018-03-13 13:38

 MOT test number
 917776576801

 Result
 ✓ Passed

 Advice
 Brake pad(s) wearing thin all (3.5.1g)

MOT #7

MOT test number

Fail Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

Advice Brake pad(s) wearing thin all (3.5.1g)

MOT test number

S42464975594

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #5

MOT test number

Result

MOT #4

MOT test number

2014-11-13 09:41

MOT test number

375607814342

Result

Notice

O/s rear brake slightly binding

CarCheck.co.uk page 4/12



MOT #3

MOT test number

Fesult

Pass with rectification

Offside Headlamp aim too low (1.8)

Notice

O/s rear brake slightly binding

Pass with rectification

Nearside Headlamp aim too high (1.8)

MOT #2

MOT test number

Fesult

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

| MOT #1 | 2013-01-11 14:36 |
|-----------------|------------------|
| MOT test number | 466051013020 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12





Tax & MOT check



MOT

Expired:
12 June 2023

Tax expired: 1 December 2022

Tax status

Expired at 1 December 2022

Days left 515 days too late

MOT expiry date 12 June 2023

Full MOT history See MOT history

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

Owner history

| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates. | , <u> </u> | |
|--|--|-------------|
| Plate changes See in this check if this VOLKSWAGEN had different number plates. | VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow | |
| Plate changes See in this check if this VOLKSWAGEN had different number plates. | *************************************** | |
| Plate changes See in this check if this VOLKSWAGEN had different number plates. | | |
| Plate changes See in this check if this VOLKSWAGEN had different number plates. | | |
| Plate changes See in this check if this VOLKSWAGEN had different number plates. | | |
| Plate changes See in this check if this VOLKSWAGEN had different number plates. | | |
| Plate changes See in this check if this VOLKSWAGEN had different number plates. | | |
| See in this check if this VOLKSWAGEN had different number plates. | | More info > |
| | Plate changes | |
| Plate since | See in this check if this VOLKSWAGEN had different number plates. | |
| Plate since | Number of plates | |
| UK UK | Current registration | UK UK |
| | Plate since | |
| Plate since | Current registration | UK UK |
| | Plate since | |

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2010-01-29 |
| Last registration | 2022-06-13 |
| Complete history | See info |



| Registration #1 | 2010-01-29 | 8 mi |
|------------------|------------|-----------|
| Registration #2 | 2013-01-11 | 31.371 mi |
| Registration #3 | 2013-11-27 | 38.864 mi |
| Registration #4 | 2014-11-13 | 45.917 mi |
| Registration #5 | 2015-10-27 | 51.389 mi |
| Registration #6 | 2016-11-07 | 61.170 mi |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 97% |
| Children | 84% |
| Pedestrian | 61% |
| Safety systems | 71% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| Width | 1786 mm |
|---------------------|---------|
| Height | 1479 mm |
| Length | 4199 mm |
| Wheel base | 2578 mm |
| Kerb weight | 1266 kg |
| Max. allowed weight | 1890 kg |

Additional information

| Fuel delivery | Direct Injection |
|-----------------|------------------|
| Number of doors | 5 |
| Number of seats | 5 |
| CarChack co.uk | page 12/1 |

CarCheck.co.uk page 12/12

| Number of axles | 2 |
|-----------------|------------|
| Engine number | CAY 288810 |