



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Grey
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	181 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	175 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-09-30
Pictures	33
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-14
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	19
Total items failed	3

MOT #13	2023-10-02 11:59
MOT test number	705880123046
Result	✓ Passed
Next expiry date	2024-10-14

MOT #12	2022-10-06 08:18
MOT test number	823210874065
Result	✓ Passed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2022-10-04 09:10
MOT test number	148575263117
Result	✗ Failed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #10** 2021-10-15 12:10**MOT test number** 508870817181**Result** ✓ Passed**MOT #9** 2021-10-12 13:29**MOT test number** 205068463477**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #8** 2021-06-11 10:21**MOT test number** 919847092058**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect light misting of oil (5.3.2 (b))**Advice** Nearside Rear Suspension component pin or bush slightly worn trailing arm bush perishing (5.3.4 (a) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect light misting of oil (5.3.2 (b))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords small cuts in tread (5.2.3 (d) (i))**Advice** Offside Rear Suspension component pin or bush slightly worn trailing arm bush perishing (5.3.4 (a) (i))**MOT #7** 2021-06-11 10:21**MOT test number** 758140661035**Result** ✗ Failed

Advice Offside Rear Suspension component pin or bush slightly worn trailing arm bush perishing (5.3.4 (a) (i))

Pass with rectification Reversing lamp inoperative (4.6.1 (a))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect light misting of oil (5.3.2 (b))

Advice Nearside Rear Suspension component pin or bush slightly worn trailing arm bush perishing (5.3.4 (a) (i))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect light misting of oil (5.3.2 (b))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords small cuts in tread (5.2.3 (d) (i))

**MOT #6** 2020-06-11 10:51**MOT test number** 880901728234**Result** ✓ Passed**MOT #5** 2019-06-14 09:49**MOT test number** 457666219158**Result** ✓ Passed**MOT #4** 2018-06-15 14:15**MOT test number** 595235833887**Result** ✓ Passed**MOT #3** 2017-06-02 07:42**MOT test number** 558766673551**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Under tray fitted to underside of vehicle, obscuring some engine components.**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #2** 2016-06-21 15:29**MOT test number** 452768061155**Result** ✓ Passed**MOT #1** 2015-06-12 12:27**MOT test number** 966883865122**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
14 October 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	14 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-09
Last registration	2023-10-02
Complete history	See info



Registration #1	2012-03-09	27 mi
Registration #2	2015-06-12	23.946 mi
Registration #3	2016-06-21	33.902 mi
Registration #4	2017-06-02	43.426 mi
Registration #5	2018-06-15	54.239 mi
Registration #6	2019-06-14	62.800 mi
Registration #7	2020-06-11	70.277 mi
Registration #8	2021-06-11	76.415 mi
Registration #9	2022-06-11	82.553 mi
Registration #10	2023-06-11	88.691 mi
Registration #11	2024-06-11	94.829 mi
Registration #12	2025-06-11	100.967 mi
Registration #13	2026-06-11	107.105 mi
Registration #14	2027-06-11	113.243 mi
Registration #15	2028-06-11	119.381 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1747 mm
Length	4576 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	145854K