





report date: 2024-03-28

#### General information

Make	FORD
Model	FOCUS ZETEC TDCI
Colour	Silver
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-28

# Internet history

#### Entry 1

Date 2021-01-30

Pictures 6

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



GU59NXB report date: 2024-03-28

MOT history

MOT expiry date	2025-02-04
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	21
Total items failed	6

MOT #19	2024-01-08 08:33
MOT test number	831340771790
Result	<b>✓</b> Passed
Next expiry date	2025-02-04
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #18	2023-01-30 12:16
MOT test number	341771723447
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #17	2023-01-30 12:16
MOT test number	911987662243
Result	<b>★</b> Failed
Pass with rectification lamps (4.7.1 (b) (ii))	Offside Registration plate lamp inoperative in the case of a single lamp or all
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification	Windscreen washer not working (3.5 (a))

MOT #16	2022-01-27 13:29
MOT test number	230606971181
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #15** 2021-02-05 11:52

**MOT test number** 830435662511

**Result** ✓ Passed

**MOT #14** 2021-02-01 10:36

**MOT test number** 672881455260

Result X Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both front brake disc inner faces (1.1.14 (a) (ii))

**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #13** 2020-09-01 13:48

**MOT test number** 424491386106

Result 

Passed

**Advice** Both front tyres wearing on inner edges of tread

Advice Steering system slightly rough Both McPherson stut upper support bearings notchy (2.1.1 (a))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12 2020-09-01 13:48

MOT test number 809051734308

Result × Failed

**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Steering system slightly rough Both McPherson stut upper support bearings notchy (2.1.1 (a))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Both front tyres wearing on inner edges of tread

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28

**MOT #11** 2019-08-30 09:24

MOT test number 978865657520

**Result** ✓ Passed

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2019-08-23 14:14

MOT test number 978228518877

**Result** X Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MAJOR Nearside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))

MOT #9 2018-08-24 13:24

MOT test number 238908338761

Result \( \sqrt{Passed} \)

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #8 2018-08-24 13:24

**MOT test number** 619766641022

Result X Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Pass with rectification

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #7	2017-08-15 08:45
MOT test number	470557549080
Result	✓ Passed
MOT #6	2016-09-09 14:08
MOT test number	466087469824
Result	✓ Passed
MOT #5	2016-09-05 14:58
MOT test number	429385994593
Result	<b>×</b> Failed
Fail Centre Seat belt cut sufficient to obstruct correct operation of the belt (5.2.2a)	
MOT #4	2015-08-17 11:51
MOT test number	499578642859
Result	✓ Passed
***	221122121

MOT #3	2014-08-18 14:54
MOT test number	386990834424
Result	✓ Passed

MOT #2	2013-08-13 11:29
MOT test number	876105123250
Result	✓ Passed

MOT #1	2012-09-11 13:31
MOT test number	405825752284
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/13



GU59NXB report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	368
MOT expiry date	4 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

*		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		ave?
THE STATE OF THE S		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	NK NK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-11
Last registration	2024-01-08
Complete history	See info



Registration #1	2009-09-11	7 mi
Registration #2	2012-09-11	20.247 mi
Registration #3	2013-08-13	24.958 mi
Registration #4	2014-08-18	30.831 mi
Registration #5	2015-08-17	37.741 mi
Registration #6	2016-09-05	41.151 mi
Registration #7	2016-09-09	41.151 mi
Registration #8	2017-08-15	54.066 mi
Registration #9	2018-08-24	62.968 mi
Registration #10	2018-08-24	62.968 mi
Registration #11	2019-08-23	70.070 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
50569	

## Safety ratings

NCAP rating	***
Video	see crash video



## Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1171 kg
Max. allowed weight	1675 kg

# Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	5	
Number of axles Carcheck.co.uk	2	page 13/13