





# General information

Make	MINI
Model	MINI (R60) COOPER S
Colour	White
Year of manufacture	2011
Top speed	133 mph
0 - 60 mph	7.4 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	190 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption combined	44.8 mpg
CO2 emission	143 g/km
CO2 label	F






# Internet history Entry 2 Date 2023-08-12 **Pictures** 14 Listing price View report Cimpsons CAR SAL AWAITING PREPARATION PHOTOS TO FOLLOW source: cargurus.co.uk Entry 1 Date 2021-07-28 **Pictures** 28 Listing price View report



source: autotrader.co.uk









## MOT history

MOT expiry date	2024-09-11
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	10
Total items failed	4

MOT #14	2023-09-12 08:25
MOT test number	740492413459
Result	✓ Passed
Next expiry date	2024-09-11

MOT #13	2022-08-09 15:30
MOT test number	404281237665
Result	✓ Passed
Advice Nearside Rear Nail in tyre nail in tyre on inner edge	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge tyre slightly worn/out of shape on inner edge (5.2.3 (e))	

MOT #12	2022-07-22 07:48
MOT test number	703051739009
Result	🗙 Failed
Fail Offside Rear Outer Seat belt damaged seat belt webbing split (7.1.2 (b) (i))	

MOT #11	2021-07-28 08:04
MOT test number	213883157776
Result	✓ Passed





MOT #10	2020-10-19 09:07
MOT test number	627540969239
Result	✓ Passed
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9	2019-10-17 11:39
MOT test number	627676205188
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #8		2019-10-17 11:39
MOT test number		507879120267
Result		🗙 Failed
Advice Oil leak, but not	excessive (8.4.1 (a) (i))	
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #7	2018-10-24 12:31
MOT test number	183027937453
Result	✓ Passed

МОТ #6	2018-01-05 11:51
MOT test number	376237839828
Result	✓ Passed





MOT #5	2018-01-05 11:29
MOT test number	346227987716
Result	🗙 Failed
Fail Headlamp cleaning device inoperative (1.7.2)	
MOT #4	2017-01-13 13:59
MOT test number	677600607814
Result	Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #3	2016-01-07 15:02
MOT test number	695593395679
Result	✓ Passed

MOT #2		2016-01-07 15:02
MOT test number		205400795730
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too high (1.8)	

MOT #1	2014-12-12 10:46
MOT test number	338616744376
Result	✓ Passed
Notice Nail in nearside rear tyre	





Tax & MOT check

✓ Taxed	✓ MOT Expires:
1 October 2024 Tax status	11 September 2024 Valid until 1 October
Days left	155
MOT expiry date	11 September 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lashe
Туре	
Damage 2	AMPLE
Damage 2	E CUT D
Date	 *
Category	 amer
Туре	

#### Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
************	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-12-30
Last registration	2023-09-12
Complete history	See info



Registration #1	2011-12-30	24 mi
Registration #2	2014-12-12	14.850 mi
Registration #3	2016-01-07	20.260 mi
Registration #4	2016-01-07	20.260 mi
Registration #5	2017-01-13	22.903 mi
Registration #6	2018-01-05	26.029 mi
Registration #7	2018-01-05	26.029 mi
Registration #8	2018-10-24	28.388 mi
Registration #9	2019-10-17	35.086 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi





# Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1789 mm
Height	1577 mm
Length	4097 mm
Kerb weight	1310 kg
Max. allowed weight	1780 kg
Additional information	
Fuel tank capacity	47
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number CarCheck.co.uk	A431I943 page 12/12