





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TIGUAN SE TDI
Colour	White
Year of manufacture	2018
Top speed	127 mph
0 - 100 km/h	9.3 seconds
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	126 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

		1
ᆮ	HLIV	-

Elitiy 1	
Date	2021-12-01
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-11-11
MOT pass rate	50 %
MOT passed	3
Failed MOT tests	3
Total advice items	18
Total items failed	6

MOT #6		2023-11-08 14:25
MOT test	number	738166491926
Result		✓ Passed
Next expi	ry date	2024-11-11
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #5	2023-11-08 10:52
MOT test number	900778227895
Result	× Failed
Fail Offside Rear Brake disc in such a condition that it is seriously weakened (1	.1.14 (a) (ii))
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Rear Brake disc in such a condition that it is seriously weakened ((1.1.14 (a) (ii))
Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #4 2022-11-09 14:55 899029789029 **MOT** test number Result ✓ Passed **Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Advice Central Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3 2022-11-09 12:40 863050589376 **MOT** test number Result ★ Failed Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail **Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2	2021-11-12 05:04
MOT test number	448061303063
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



MOT

Tax status	Valid until 1 February
Days left	279
MOT expiry date	11 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history

, ,	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	AIS UK
Plate since	
Current registration	NIP. UK
Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-11-05
Last registration	2023-11-08
Complete history	See info



Registration #1	2018-11-05	22 mi
Registration #2	2021-11-11	14.145 mi
Registration #3	2021-11-12	14.145 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	96%
Children	84%
Pedestrian	72%
Safety systems	68%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2099 mm
Height	1632 mm
Length	4486 mm
Wheel base	2677 mm
Kerb weight	1568 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack caluk	page 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	DFGA877015