



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Silver
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 2

Date	2021-09-14
Pictures	0
Listing price	View report

source: autotrader.co.uk

Entry 1

Date	2021-08-27
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-31
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	22
Total items failed	8

MOT #102023-08-31 15:40

MOT test number946068274178

Result✓ Passed

Next expiry date2024-08-31

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9**

2023-08-31 08:22

MOT test number

685233449071

Result**✗ Failed****Minor**

Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Fail

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8

2022-09-01 12:19

MOT test number

438605200013

Result**✓ Passed****Advice**

Nearside Rear Lower Suspension component pin or bush slightly worn hub bush (5.3.4 (a) (i))

Advice

Offside Rear Lower Suspension component pin or bush slightly worn hub bush (5.3.4 (a) (i))

**MOT #7** 2022-08-29 12:29**MOT test number** 203750319888**Result** ✗ Failed

- Fail** Nearside Rear Lower Suspension arm pin or bush excessively worn trailing arm front bush (5.3.4 (a) (i))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Lower Suspension component pin or bush slightly worn hub bush (5.3.4 (a) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Rear Lower Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Lower Suspension component pin or bush slightly worn hub bush (5.3.4 (a) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #6 2021-08-31 09:32**MOT test number** 908579345710**Result** ✓ Passed**MOT #5** 2020-12-08 18:07**MOT test number** 311086559309**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2019-05-30 15:39**MOT test number** 602017236230**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #3	2017-12-21 16:52
MOT test number	269514665183
Result	✓ Passed

MOT #2	2016-12-15 14:55
MOT test number	872520595386
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2015-12-17 10:34
MOT test number	457582990018
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
31 August 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 CA62EPX
Plate since	2019-09-29
Current registration	 CA62EPX
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-12-27
Last registration	2023-08-31
Complete history	See info



Registration #1	2012-12-27	10 mi
Registration #2	2015-12-17	17.666 mi
Registration #3	2016-12-15	22.988 mi
Registration #4	2017-12-21	27.879 mi
Registration #5	2019-05-30	30.410 mi
Registration #6	2020-12-08	36.002 mi
Registration #7	2022-05-20	39.277 mi
Registration #8	2022-05-20	39.277 mi
Registration #9	2022-05-20	39.277 mi
Registration #10	2022-05-20	39.277 mi
Registration #11	2022-05-20	39.277 mi
Registration #12	2022-05-20	39.277 mi
Registration #13	2023-08-31	39.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	202373K