






report date: 2024-03-29

### General information

Make	NISSAN
Model	NV200 DCI SE
Colour	White
Year of manufacture	2012
Top speed	98 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	58.9 mpg
Consumption combined	55.4 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

### Entry 1

Date 2021-12-09

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

## MOT history

MOT expiry date	2024-12-19
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	14
Total items failed	10

MOT #15		2023-12-07 13:54
MOT test nui	mber	958956402266
Result		✓ Passed
Next expiry	date	2024-12-19
<b>Advice</b> N	earside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice No.	earside Front Brake disc worn, pitted or scored, but not seriously weake	ned inner face (1.1.14 (a)
<b>Advice</b> St	uspension arm ball joint has slight play both front lowers (5.3.4 (a) (i))	
<b>Minor</b> Off	fside Obligatory mirror slightly damaged (3.3 (b) (i))	
<b>Advice</b> N	earside Rear leaf spring corroded	

MOT #14		2023-12-07 13:54
MOT test number		213668295011
Result		<b>X</b> Failed
Minor Offside Oblig	gatory mirror slightly damaged (3.3 (b) (i))	
Pass with rectificati	ion Supplementary restraint system warning lamp in	dicates a fault (7.1.6 (a))
Advice Nearside Re	ear leaf spring corroded	
<b>Advice</b> Suspension	arm ball joint has slight play both front lowers (5.3.4 (a	a) (i))
Advice Nearside From (ii))	ont Brake disc worn, pitted or scored, but not seriously	weakened inner face (1.1.14 (a)
<b>Advice</b> Nearside Re	ear Direction indicator slightly discoloured (4.4.3 (a))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13		2022-12-12 15:37
MOT test	number	932038587894
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	
Advice	Front Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))	
Advice	Both headlights deteriorated	

MOT #12	2021-12-17 12:04
MOT test number	509038238226
Result	<b>✓</b> Passed
MOT #11	2021-12-16 16:17
MOT test number	166067787204
Result	<b>X</b> Failed
Fail Offside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	

MOT #10	2020-12-01 13:36
MOT test number	110693388274
Result	<b>✓</b> Passed
Advice Rear brakes juddering slightly	

MOT #9	2019-11-21 10:07
MOT test number	191219431236
Result	✓ Passed
MOT #8	2018-12-20 14:22
MOT test number	118433965972
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #7 2018-12-20 10:21
MOT test number 704546570802

**Result** X Failed

**Fail** Reversing lamp inoperative (4.6.1 (a))

MOT #6 2017-12-13 11:19

**MOT test number** 320665106931

**Result** ✓ Passed

MOT #5 2017-01-03 10:23

**MOT test number** 428896754980

**Result** ✓ Passed

MOT #4 2016-01-11 15:20

**MOT test number** 600488675075

Result 

Passed

MOT #3 2016-01-11 11:06

**MOT test number** 284082594749

Result X Failed

**Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)

**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)

**Pass with rectification** Headlamp aim too high both (1.8)

**Fail** Nearside rear brake recording little or no effort (3.7.B.5a)

**Fail** Front position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance both dim (1.1.A.3d)

MOT #2 2015-01-21 10:03

MOT test number 528961425068

CarCheck.co.uk page 5/13



FH61EKW report date: 2024-03-29

MOT #1 2015-01-20 13:21

**MOT test number** 679070425031

Result

**X** Failed

Fail Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

Fail Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 6/13



report date: 2024-03-29





MOT expiry date 19 December 2024

Full MOT history See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

$\sim$			
Own	or h	1St	าrv
	וו וט	IJU	יוע

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full		ιN
manus .		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this NISSAN had different number plates.		
Number of plates		
Current registration	NK NK	
Flate since		
Current registration	NK NK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-01-31
Last registration	2023-12-07
Complete history	See info



Registration #1	2012-01-31	17 mi
Registration #2	2015-01-20	64.749 mi
Registration #3	2015-01-21	64.749 mi
Registration #4	2016-01-11	71.347 mi
Registration #5	2016-01-11	71.347 mi
Registration #6	2017-01-03	77.024 mi
Registration #7	2017-12-13	80.483 mi
Registration #8	2018-12-20	81.985 mi
Registration #9	2018-12-20	81.992 mi
Registration #10		11.177 es
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		11.177 mi
Registration #14		11.117 es
Registration #15		
		11.777 es
Registration #16		11.777 ea

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	2011 mm
Height	1860 mm
Length	4400 mm
Kerb weight	1261 kg
Max. allowed weight	2000 kg

## Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Number of axles	2
Engine number	K9K-020445

CarCheck.co.uk page 13/13