



YO15YRR


report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO SE TSI
Colour	White
Year of manufacture	2015
Top speed	114 mph
0 - 100 km/h	10.8 seconds
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 kW / 90 HP / 89 BHP
Max. torque	160 Nm at 1.400 rpm
Engine capacity	1.197 cc
Cylinders	4
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	107 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-01-29
Pictures	26
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-01-21
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	12
Total items failed	9

MOT #10	2024-01-22 12:17
MOT test number	248508261101
Result	✓ Passed
Next expiry date	2025-01-21

MOT #9	2023-01-10 16:43
MOT test number	402662458133
Result	✓ Passed

MOT #8	2021-10-28 09:06
MOT test number	624458975420
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #7** 2021-10-27 12:49**MOT test number** 457000361541**Result** ✗ Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords various cuts (5.2.3 (d) (i))

Fail Offside Front Tyre tread depth below requirements of 1.6mm cords exposed (5.2.3 (e))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #6 2020-10-26 11:44**MOT test number** 565278287110**Result** ✓ Passed**MOT #5** 2020-10-26 11:10**MOT test number** 191788974684**Result** ✗ Failed

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #4 2019-09-13 09:34**MOT test number** 748309147371**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #3** 2019-09-13 09:34**MOT test number** 576102960271**Result** ✗ Failed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2018-09-13 07:30**MOT test number** 377466530656**Result** ✓ Passed**MOT #1** 2018-09-03 17:51**MOT test number** 775270267278**Result** ✗ Failed

- Fail** Offside Rear Position lamp not working (4.2.1 (a))
- Fail** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm 185/60/15 (5.2.3 (e))
- Fail** Rear fog lamp not working (4.5.1 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
21 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-01-01
Current registration	 XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-08-13
Last registration	2024-01-22
Complete history	See info



Registration #1	2015-08-13	27 mi
Registration #2	2018-09-03	42.792 mi
Registration #3	2018-09-13	42.792 mi
Registration #4	2019-09-13	50.655 mi
Registration #5	2019-09-13	50.655 mi
Registration #6	2020-10-26	59.016 mi
Registration #7	2020-10-26	59.016 mi
Registration #8	2020-10-26	59.016 mi
Registration #9	2020-10-26	59.016 mi
Registration #10	2020-10-26	59.016 mi
Registration #11	2020-10-26	59.016 mi
Registration #12	2020-10-26	59.016 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1901 mm
Height	1462 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1007 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles	2
Engine number	CJZC437240