



report date: 2024-03-29

General information

Make	SUZUKI
Model	GRAND VITARA VVT +
Colour	Blue
Year of manufacture	2007
Top speed	99 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	145 Nm at 4.100 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	37.2 mpg
Consumption combined	32.5 mpg
CO2 emission	210 g/km
CO2 label	K





## MOT history

MOT expiry date	2025-03-01
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	34
Total items failed	3

MOT #19	2024-02-28 12:03
MOT test number	765885139750
Result	✓ Passed
Next expiry date	2025-03-01

MOT #18	2023-03-02 15:33
MOT test number	984162778343
Result	✓ Passed

MOT #17	2023-02-28 13:00
MOT test number	130191959866
Result	✗ Failed
<b>MAJOR</b> Offside Front Position lamp not working (4.2.1 (a) (ii))	
<b>MAJOR</b> Nearside Front Position lamp not working (4.2.1 (a) (ii))	
<b>MAJOR</b> Central Exhaust system insecure (6.1.2 (a))	

MOT #16	2022-01-27 15:32
MOT test number	933381657708
Result	✓ Passed

**MOT #15** 2021-04-28 14:34**MOT test number** 125975626539**Result** ✓ Passed**Advice** Fuel Pipe/s corroded**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**MOT #14** 2020-06-20 14:57**MOT test number** 297310492618**Result** ✓ Passed**MOT #13** 2019-03-04 11:51**MOT test number** 345740385087**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))



MOT #12

2018-03-09 16:03

MOT test number

168174276712

Result

✓ Passed

- Advice

Nearside Front Outer tyre going out of shape
- Advice

Body has slight corrosion various underbody areas /locations (6.1.B.2)
- Advice

Nearside Rear Outer edge of tyre worn
- Advice

Brake hose has slight corrosion to ferrules various areas / locations (3.6.B.4e)
- Advice

Nearside Rear Lower Fuel Pipe/s corroded
- Advice

Offside Front Outer tyre going out of shape
- Advice

Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Rear Outer edge of tyre worn
- Advice

Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' stone chips (8.3.1d)

**MOT #11**

2018-03-09 16:03

**MOT test number**

554762549964

**Result****✗ Failed**

- Advice** Nearside Rear Outer edge of tyre worn
- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' stone chips (8.3.1d)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Outer tyre going out of shape
- Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Rear Outer edge of tyre worn
- Advice** Nearside Rear Lower Fuel Pipe/s corroded
- Advice** Body has slight corrosion various underbody areas /locations (6.1.B.2)
- Advice** Nearside Front Outer tyre going out of shape
- Advice** Brake hose has slight corrosion to ferrules various areas / locations (3.6.B.4e)

**MOT #10**

2017-03-08 12:05

**MOT test number**

752804842628

**Result****✓ Passed**

- Advice** Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)

**MOT #9**

2017-03-04 12:25

**MOT test number**

221157122054

**Result****✗ Failed**

- Fail** Nearside Rear wheel bearing has excessive play (2.6.2)
- Advice** Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)

**MOT #8** 2016-03-08 13:26**MOT test number** 700912804564**Result** ✓ Passed**Advice** Rear exhaust hanger broken**MOT #7** 2015-03-12 16:21**MOT test number** 617741775096**Result** ✓ Passed**MOT #6** 2014-03-12 11:27**MOT test number** 805801974077**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-03-05 10:39**MOT test number** 596594163057**Result** ✓ Passed**MOT #4** 2012-02-17 13:33**MOT test number** 105308342488**Result** ✓ Passed**MOT #3** 2011-02-25 12:40**MOT test number** 199046751006**Result** ✓ Passed**Notice** Wipers smear slightly



MOT #2	2010-02-26 14:10
MOT test number	250227550051
Result	✓ Passed

MOT #1	2010-02-26 13:19
MOT test number	101127150097
Result	✗ Failed
<div><div>Advice</div> Nearside Rear Tyre worn close to the legal limit (4.1.E.1)</div> <div><div>Fail</div> Offside Rear Stop lamp not working (1.2.1b)</div> <div><div>Advice</div> Offside Rear Tyre worn close to the legal limit (4.1.E.1)</div>	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
1 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	1 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>KY07VDZ</b>
Plate since	2019-03-29
Current registration	<b>KY07VDZ</b>
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-05
Last registration	2024-02-28
Complete history	<a href="#">See info</a>



Registration #1	2007-03-05	7 mi
Registration #2	2010-02-26	30.190 mi
Registration #3	2010-02-26	30.190 mi
Registration #4	2011-02-25	42.668 mi
Registration #5	2012-02-17	54.260 mi
Registration #6	2013-03-05	66.906 mi
Registration #7	2014-03-12	70.221 mi
Registration #8	2015-03-12	73.672 mi
Registration #9	2016-03-08	77.050 mi
Registration #10	2017-03-04	79.991 mi
Registration #11	2018-03-01	82.932 mi
Registration #12	2019-03-01	85.873 mi
Registration #13	2020-03-01	88.814 mi
Registration #14	2021-03-01	91.755 mi
Registration #15	2022-03-01	94.696 mi
Registration #16	2023-03-01	97.637 mi
Registration #17	2024-03-01	100.578 mi
Registration #18	2025-03-01	103.519 mi
Registration #19	2026-03-01	106.460 mi
Registration #20	2027-03-01	109.401 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1695 mm
Length	4005 mm
Wheel base	2440 mm
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M16A-1140340