



report date: 2024-03-28

## General information

Make	VOLVO
Model	V70 D3 SE
Colour	White
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	163 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	51.4 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 2


Date	2021-02-06
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-29
Pictures	17
Listing price	<a href="#">View report</a>



source: [yesauto.com](#)



MOT history

MOT expiry date	2024-06-21
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	17
Total items failed	1

MOT #13	2023-06-20 08:47
MOT test number	704454866059
Result	✓ Passed
Next expiry date	2024-06-21
Advice	ENGINE COVERS FITTED NOT ALLOWING FULL INSPECTION OF THE ENGINE BAY AREA
Advice	SILL COVERS FITTED NOT ALLOWING FULL INSPECTION OF THE SILL AREA

MOT #12	2022-06-09 10:43
MOT test number	833298954346
Result	✓ Passed

MOT #11	2021-06-22 12:46
MOT test number	147402346779
Result	✓ Passed

**MOT #10** 2021-06-18 12:07**MOT test number** 581959573071**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #9** 2020-07-28 08:55**MOT test number** 872329332179**Result** ✓ Passed**MOT #8** 2019-07-11 08:11**MOT test number** 970638624740**Result** ✓ Passed**MOT #7** 2018-07-20 08:56**MOT test number** 719360436706**Result** ✓ Passed**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))**Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))**MOT #6** 2017-07-13 08:22**MOT test number** 127587722515**Result** ✓ Passed**Advice** Nearside Rear Inner Tyre worn close to the legal limit edge scrubbing (4.1.E.1)**Advice** Offside Rear Inner Tyre worn close to the legal limit edge scrubbing (4.1.E.1)

**MOT #5** 2016-07-14 13:00**MOT test number** 209163155785**Result** ✓ Passed**MOT #4** 2015-07-30 13:34**MOT test number** 365361415233**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2015-07-29 11:22**MOT test number** 145920915282**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear tyres wearing uneven on inner edges**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2014-08-11 13:54**MOT test number** 698953324245**Result** ✓ Passed**MOT #1** 2013-09-05 17:13**MOT test number** 839308243293**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
21 June 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	21 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YH60KLL
Plate since	2019-09-28
Current registration	YH60KLL
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-30
Last registration	2023-06-20
Complete history	<a href="#">See info</a>



Registration #1	2010-09-30	10 mi
Registration #2	2013-09-05	55.843 mi
Registration #3	2014-08-11	70.485 mi
Registration #4	2015-07-29	88.740 mi
Registration #5	2015-07-30	88.741 mi
Registration #6	2016-07-14	105.618 mi
Registration #7	2017-07-13	117.911 mi
Registration #8	2018-07-20	130.444 mi
Registration #9	2019-06-20	151.277 mi
Registration #10	2019-06-20	151.277 mi
Registration #11	2019-06-20	151.277 mi
Registration #12	2019-06-20	151.277 mi
Registration #13	2019-06-20	151.277 mi
Registration #14	2019-06-20	151.277 mi
Registration #15	2019-06-20	151.277 mi
Registration #16	2019-06-20	151.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1643 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Engine number**

870929