



report date: 2024-03-29

General information

Make	KIA
Model	VENGA 3
Colour	Silver
Year of manufacture	2011
Top speed	110 mph
0 - 60 mph	11.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	123 BHP
Max. torque	156 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G



Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-11-01
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	30
Total items failed	16

MOT #17	2023-11-01 15:24
MOT test number	838891475377
Result	✓ Passed
Next expiry date	2024-11-01
Advice	Oil leak, but not excessive gearbox (8.4.1 (a) (i))
Advice	Brake disc worn, but not excessively both rear (1.1.14 (a) (i))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Advice	Coil spring corroded both rear (5.3.1 (b) (i))

MOT #16	2023-11-01 15:24
MOT test number	959978414781
Result	✗ Failed
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Oil leak, but not excessive gearbox (8.4.1 (a) (i))
Advice	Brake disc worn, but not excessively both rear (1.1.14 (a) (i))
Pass with rectification	Offside Side repeater incorrect colour (4.4.3 (a))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Advice	Coil spring corroded both rear (5.3.1 (b) (i))
Pass with rectification	Nearside Side repeater incorrect colour (4.4.3 (a))

**MOT #15**

2022-10-26 12:07

MOT test number

681568213701

Result

✓ Passed

Advice Offside Side repeater slightly discoloured (4.4.3 (a))**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))**Advice** Tyre slightly damaged/cracking or perishing both rears perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14**

2022-10-26 12:07

MOT test number

299395793624

Result

✗ Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))**Advice** Tyre slightly damaged/cracking or perishing both rears perishing (5.2.3 (d) (ii))**Advice** Offside Side repeater slightly discoloured (4.4.3 (a))**MOT #13**

2021-11-02 15:38

MOT test number

228333392665

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm and bald inner edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm and bald inner edge (5.2.3 (e))**Advice** Offside Front Nail in tyre

**MOT #12**

2021-11-01 17:29

MOT test number

395858881447

Result**✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm and bald inner edge (5.2.3 (e))**Advice** Items removed from driver's view prior to test**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm and bald inner edge (5.2.3 (e))**Advice** Offside Front Nail in tyre**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #11**

2020-10-09 12:27

MOT test number

896344656427

Result**✓ Passed****MOT #10**

2020-10-09 12:27

MOT test number

335893214226

Result**✗ Failed****Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Offside Side repeater incorrect colour (4.4.3 (a))**Pass with rectification** Nearside Side repeater incorrect colour (4.4.3 (a))**MOT #9**

2019-05-02 12:42

MOT test number

487696544559

Result**✓ Passed**

**MOT #8** 2019-05-01 13:09**MOT test number** 798717687822**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**MOT #7** 2018-04-16 12:37**MOT test number** 182747195619**Result** ✓ Passed**MOT #6** 2017-04-13 13:02**MOT test number** 691600042330**Result** ✓ Passed**MOT #5** 2016-04-25 13:39**MOT test number** 439120048582**Result** ✓ Passed**Advice** Offside Side repeater slightly discoloured (1.4.A.2f)**MOT #4** 2016-04-25 12:01**MOT test number** 686684142120**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Side repeater slightly discoloured (1.4.A.2f)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #3** 2015-04-07 11:16**MOT test number** 835947395063**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2015-04-07 11:16**MOT test number** 177447095460**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Offside Rear fog lamp not working (1.3.2b)**MOT #1** 2014-04-02 13:58**MOT test number** 616682694015**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.D.4)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
1 November 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-04-28
Last registration	2023-11-01
Complete history	See info



Registration #1	2011-04-28	28 mi
Registration #2	2014-04-02	25.346 mi
Registration #3	2015-04-07	32.269 mi
Registration #4	2016-04-25	39.763 mi
Registration #5	2016-04-25	39.771 mi
Registration #6	2017-04-13	45.644 mi
Registration #7	2018-04-16	50.507 mi
Registration #8	2019-05-01	54.648 mi
Registration #9	2019-05-02	54.651 mi
Registration #10	2019-05-02	54.651 mi
Registration #11	2019-05-02	54.651 mi
Registration #12	2019-05-02	54.651 mi
Registration #13	2019-05-02	54.651 mi
Registration #14	2019-05-02	54.651 mi
Registration #15	2019-05-02	54.651 mi
Registration #16	2019-05-02	54.651 mi
Registration #17	2019-05-02	54.651 mi
Registration #18	2019-05-02	54.651 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4068 mm
Wheel base	2615 mm
Kerb weight	1269 kg
Max. allowed weight	1730 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FCAZ200501