



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT SE TDI
Colour	Silver
Year of manufacture	-
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #12</b>	2020-06-30 16:09
<b>MOT test number</b>	310986224704
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-06-29
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #11</b>	2019-06-03 13:19
<b>MOT test number</b>	861497678390
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #10</b>	2019-06-03 12:44
<b>MOT test number</b>	376844056432
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Fail</b>	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

<b>MOT #9</b>	2018-06-07 11:33
<b>MOT test number</b>	265100150945
<b>Result</b>	✓ Passed

<b>MOT #8</b>	2017-06-08 10:15
<b>MOT test number</b>	292072494481
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Central Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #7** 2016-06-09 10:21**MOT test number** 240962041077**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-06-11 14:24**MOT test number** 356852965182**Result** ✓ Passed**Advice** Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #5** 2014-05-29 11:34**MOT test number** 296099144116**Result** ✓ Passed**MOT #4** 2013-05-30 09:02**MOT test number** 897910853136**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-06-08 17:01**MOT test number** 435420062190**Result** ✓ Passed



MOT #2		2012-06-08 17:01
MOT test number		556400162179
Result		✗ Failed
Pass with rectification	Offside Front Headlamp aim too low (1.8)	
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Pass with rectification	Nearside Rear Wheel bolt(s) missing (4.2.A.1e)	

MOT #1		2011-06-01 15:30
MOT test number		459012951174
Result		✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 NV08UXN
Plate since	2019-03-29
Current registration	 NV08UXN
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2008-06-09
Last registration	2020-06-30
Complete history	<a href="#">See info</a>



Registration #1	2008-06-09	20 mi
Registration #2	2011-06-01	39.147 mi
Registration #3	2012-06-08	51.251 mi
Registration #4	2013-05-30	64.468 mi
Registration #5	2014-05-29	71.988 mi
Registration #6	2015-06-11	78.786 mi
Registration #7	2016-06-01	85.584 mi
Registration #8	2017-06-01	92.382 mi
Registration #9	2018-06-01	99.180 mi
Registration #10	2019-06-01	105.978 mi
Registration #11	2020-06-30	112.776 mi
Registration #12	2021-06-01	119.574 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1454 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 056163