



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 D P/V
Colour	Black
Year of manufacture	-
Gearbox	4 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	at 2.500 rpm
Cylinders	4
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-19
Pictures	0
Listing price	View report

source: autotrader.co.uk

**MOT history**

MOT #18	2021-08-13 14:50
MOT test number	915670212612
Result	✓ Passed
Next expiry date	2022-08-12
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2021-08-12 07:05
MOT test number	323819615701
Result	✗ Failed
Fail	Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Fail	Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Rear Direction indicator not working (4.4.1 (a) (ii))

MOT #16	2018-09-17 10:22
MOT test number	630598144875
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15**

2017-07-26 15:04

MOT test number

972158066855

Result

✓ Passed

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Eml on**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #14**

2017-07-18 13:28

MOT test number

125916503879

Result

✗ Failed

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Rear position lamp(s) obscured more than 50% (1.1.A.3c)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm cordes exposed (4.1.E.1)**Advice** Eml on**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Service brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #13** 2015-12-03 10:38**MOT test number** 717864057692**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin both sides (3.5.1g)**MOT #12** 2015-12-02 13:15**MOT test number** 333402134272**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin both sides (3.5.1g)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm to cord (4.1.E.1)**MOT #11** 2014-12-12 16:38**MOT test number** 108506244352**Result** ✓ Passed**MOT #10** 2013-12-04 09:33**MOT test number** 858528433338**Result** ✓ Passed**MOT #9** 2012-11-14 15:32**MOT test number** 469359212368**Result** ✓ Passed**MOT #8** 2011-11-10 16:39**MOT test number** 378704511332**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

**MOT #7** 2010-11-19 17:10**MOT test number** 183453320337**Result** ✓ Passed**MOT #6** 2010-11-18 17:43**MOT test number** 783282720357**Result** ✗ Failed

- Fail** Offside Brake pipe excessively corroded (3.6.B.2c)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Rear Rear wheel bearing has excessive play (2.6.2)

MOT #5 2009-11-19 12:51**MOT test number** 324823529349**Result** ✓ Passed

- Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)
- Notice** All locking wheel nuts are to short

MOT #4 2009-11-19 11:14**MOT test number** 641483729350**Result** ✗ Failed

- Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)
- Notice** All locking wheel nuts are to short
- Fail** Rear Exhaust system not adequately supported (7.1.1)
- Fail** Offside Side repeater incorrect colour (1.4.A.2f)

MOT #3 2008-06-09 14:47**MOT test number** 991821968197**Result** ✓ Passed



MOT #2	2007-07-25 12:01
MOT test number	122726307266
Result	✓ Passed
MOT #1	2007-02-02 10:51
MOT test number	100283937036
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2002-10-09
Last registration	2021-08-13
Complete history	See info



Registration #1	2002-10-09	16 mi
Registration #2	2007-02-02	30.466 mi
Registration #3	2007-07-25	32.902 mi
Registration #4	2008-06-09	38.376 mi
Registration #5	2009-11-19	45.707 mi
Registration #6	2009-11-19	45.707 mi
Registration #7	2010-11-18	51.036 mi
Registration #8	2010-11-19	51.036 mi
Registration #9	2011-11-10	55.519 mi
Registration #10	2012-11-14	58.912 mi
Registration #11	2013-05-20	61.377 mi
Registration #12	2013-05-20	61.377 mi
Registration #13	2013-05-20	61.377 mi
Registration #14	2013-05-20	61.377 mi
Registration #15	2013-05-20	61.377 mi
Registration #16	2013-05-20	61.377 mi
Registration #17	2013-05-20	61.377 mi
Registration #18	2013-05-20	61.377 mi
Registration #19	2013-05-20	61.377 mi
Registration #20	2013-05-20	61.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Fuel delivery	Indirect Injection
Number of axles	2
Engine number	NOT KNOWN