





report date: 2024-03-29

General information

Make	MERCEDES
Model	ML ML 280 CDI EDITION S
Colour	Black
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	440 Nm at 2.800 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	35.3 mpg
Consumption combined	28.8 mpg
CO2 emission	254 g/km
CO2 label	L



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/14



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-02-25
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	29
Total items failed	7

MOT #19	2024-02-26 15:55
MOT test number	748120701640
Result	✓ Passed
Next expiry date	2025-02-25

MOT #18	2023-02-23 11:19
MOT test number	394553384150
Result	√ Passed

MOT #17		2022-02-07 10:34
MOT test	number	253212321090
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16	2021-02-	-26 14:26
MOT test	number 29177	2566081
Result	·	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	

CarCheck.co.uk page 3/14



MOT #15 2021-02-26 11:43

MOT test number 505638372308

Result X Failed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Minor Offside Windscreen wiper blade defective smearing (3.4 (b) (i))

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Headlamps matched pair are not the same colour (4.1.4 (d))

MOT #14 2019-07-29 14:31

MOT test number 814984360913

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Under tray fitted

MOT #13 2018-10-26 11:40

MOT test number 855106908635

Result ✓ Passed

MOT #12 2017-08-23 10:21

MOT test number 579891417250

Result ✓ Passed

CarCheck.co.uk page 4/14



MOT #11

MOT test number

Result

Advice Off side parking brake low effort

Advice Oil leak

2016-08-19 09:07

202309037048

✓ Passed

MOT #10

MOT test number

Result

Advice Front under tray fitted obscuring some underside components

2015-08-25 12:57

264343148168

✓ Passed

MOT test number

Result

Pass with rectification

Offside Front position lamp(s) not working (1.1.A.3b)

Advice

Front under tray fitted obscuring some underside components

MOT #8 2015-01-07 14:31 825767405059 **MOT** test number Result Passed Notice O/s front inner sidewall damage Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Advice Rear Tyre worn close to the legal limit (4.1.E.1) Notice Oil leak **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/14



MOT #7 2014-12-27 13:06 **MOT** test number 477071664497 Result × Failed **Notice** Offside front tyre inner wall cut Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Notice Oil leak Pass with rectification Nearside Headlamp aim too high (1.8) **Notice** Nearside front tyre has outer wear Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail

MOT test number

Result

Notice Oil leak

Notice Items removed from driver's view prior to test

Notice Under-trays fitted obscuring some underside components

MOT #5 2012-12-13 17:30 **MOT test number** 188628042355 Result ✓ Passed **MOT #4** 2012-12-13 11:38 **MOT** test number 139398642337 Result × Failed Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f) Fail Fail Nearside Headlamp not working on dipped beam (1.7.5a)

CarCheck.co.uk page 6/14



MOT #3

MOT test number

Result

MOT #2

MOT test number

MOT test number

MOT test number

898413761304

Result

Pass with rectification

Offside Headlamp not working on dipped beam (1.7.5a)

MOT #1

MOT test number

617635501062

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	25 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 8/14



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	

Damage 2

Damage 2	
Date	
Category	



Extra MERCEDES salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK SIR
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-29
Last registration	2024-02-26
Complete history	See info



2007-09-29	24 mi
2011-01-05	36.552 mi
2011-12-29	43.562 mi
2012-12-13	61.170 mi
2012-12-13	61.170 mi
2013-12-09	66.570 mi
2014-12-27	77.903 mi
2015-01-07	78.188 mi
2015-08-25	83.581 mi
2015-08-25	83.581 mi
	9.70 es
	71.777 es
	11.777 es
	11.777 es
	9.70 es
	11.777 es
	9.70 es
	11.777 es
	11.777 es
	11.777 es
	2011-01-05 2011-12-29 2012-12-13 2012-12-13 2013-12-09 2014-12-27 2015-01-07 2015-08-25 2015-08-25

More info >

CarCheck.co.uk page 13/14



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1911 mm
Height	1884 mm
Length	4780 mm
Wheel base	2915 mm
Kerb weight	2185 kg

Additional information

Fuel tank capacity	95 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64294040371305

CarCheck.co.uk page 14/14