



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 URBAN LITE
Colour	Silver
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	103 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-06-14
Pictures	39
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-05
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	26
Total items failed	4

MOT #12 2023-12-06 11:20

MOT test number 429208072837

Result ✓ Passed

Next expiry date 2024-12-05

- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11 2022-12-05 12:56

MOT test number 185844048468

Result ✓ Passed

- Advice** Front Subframe mounting prescribed area is corroded but not considered excessive And Rear (5.3.6 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))
- Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- Advice** Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

**MOT #10**

2022-12-05 12:56

MOT test number

261066896220

Result

✗ Failed

Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

Advice Front Subframe mounting prescribed area is corroded but not considered excessive And Rear (5.3.6 (a) (i))

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #9

2021-11-29 15:23

MOT test number

112538204019

Result

✓ Passed

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement n/s & off/s rear (5.3.4 (a) (i))

Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both n/s & off/s (5.3.4 (a) (i))

Advice Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #8

2020-12-03 12:34

MOT test number

337434765172

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7

2019-04-18 08:45

MOT test number

915716656255

Result

✓ Passed

**MOT #6** 2018-04-17 15:06**MOT test number** 903509511317**Result** ✓ Passed**MOT #5** 2017-06-20 11:23**MOT test number** 525823025721**Result** ✓ Passed**Advice** Both front tyres**Advice** Front disks and pads**MOT #4** 2016-06-21 13:46**MOT test number** 219631535564**Result** ✓ Passed**MOT #3** 2016-06-21 10:10**MOT test number** 793008499775**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp not working Lens/cover missing (1.1.C.1d)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #2** 2015-06-08 09:42**MOT test number** 806169855154**Result** ✓ Passed



MOT #1	2014-06-19 10:42
MOT test number	179250874188
Result	✓ Passed
Notice	O/s/f tyre wearing inner edge
Notice	Rear exhaust hangers corroded



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
5 December 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	5 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	MT11EEU
Plate since	2024-03-28
Current registration	MT11EEU
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-06-22
Last registration	2023-12-06
Complete history	See info



Registration #1	2011-06-22	18 mi
Registration #2	2014-06-19	19.779 mi
Registration #3	2015-06-08	26.619 mi
Registration #4	2016-06-21	38.285 mi
Registration #5	2016-06-21	38.285 mi
Registration #6	2017-06-20	49.712 mi
Registration #7	2018-04-17	58.474 mi
Registration #8	2019-06-20	65.277 mi
Registration #9	2019-06-20	65.277 mi
Registration #10	2019-06-20	65.277 mi
Registration #11	2019-06-20	65.277 mi
Registration #12	2019-06-20	65.277 mi
Registration #13	2019-06-20	65.277 mi
Registration #14	2019-06-20	65.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7010031