



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA 16V SX
Colour	Silver
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT #18	2020-09-30 16:49
MOT test number	793634018371
Result	✓ Passed
Next expiry date	2021-10-28
Advice	Rear Brake pipe corroded, covered in grease or other material N/S & O/S (1.1.11 (c))

MOT #17	2020-09-29 10:29
MOT test number	549020926247
Result	✗ Failed
Fail	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
Fail	Front Tyre tread depth below requirements of 1.6mm N/S & O/S (5.2.3 (e))
Advice	Rear Brake pipe corroded, covered in grease or other material N/S & O/S (1.1.11 (c))
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Front Windscreen wiper does not clear the windscreen effectively N/S & O/S (3.4 (b) (ii))

MOT #16	2019-10-29 13:46
MOT test number	354397865985
Result	✓ Passed
Advice	Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #15	2019-10-29 13:46
MOT test number	205467970220
Result	✗ Failed
Advice	Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #14** 2018-10-08 10:05**MOT test number** 766908871679**Result** ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement
wishbone rear bush slight play (5.3.4 (a) (i))

MOT #13 2017-10-16 12:06**MOT test number** 906416286648**Result** ✓ Passed**MOT #12** 2016-06-06 11:40**MOT test number** 578241737068**Result** ✓ Passed**MOT #11** 2015-06-15 12:55**MOT test number** 546166165198**Result** ✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #10 2015-06-15 12:55**MOT test number** 248296965463**Result** ✗ Failed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Pass with rectification Registration plate lamp not working (1.1.C.1d)

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #9** 2014-06-11 12:06**MOT test number** 208442264136**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Rear exhaust mounting corroded

MOT #8 2014-06-11 12:06**MOT test number** 166862664111**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)
- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Rear exhaust mounting corroded
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2013-06-10 10:40**MOT test number** 515421263113**Result** ✓ Passed

- Notice** Rear exhaust bracket corroded/broken but exhaust is still supported
- Notice** Both front tyres wearing thin, and void of tread on outer edges

**MOT #6** 2013-06-10 10:40**MOT test number** 438841063173**Result** ✗ Failed**Notice** Rear exhaust bracket corroded/broken but exhaust is still supported**Notice** Both front tyres wearing thin, and void of tread on outer edges**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #5** 2012-06-19 16:23**MOT test number** 317811272150**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2012-06-19 16:23**MOT test number** 415711472178**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2011-03-15 12:04**MOT test number** 758734071006**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2010-03-16 10:09**MOT test number** 383735070086**Result** ✓ Passed



MOT #1	2010-03-11 09:50
MOT test number	984250770071
Result	✗ Failed
Fail	Front Windscreen washer provides insufficient washer liquid (8.2.3)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 UK XXXXXX
Plate since	2024-03-28
Current registration	 UK XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-03-31
Last registration	2020-09-30
Complete history	See info



Registration #1	2007-03-31	29 mi
Registration #2	2010-03-11	25.364 mi
Registration #3	2010-03-16	25.638 mi
Registration #4	2011-03-15	33.676 mi
Registration #5	2012-06-19	51.556 mi
Registration #6	2013-06-10	68.675 mi
Registration #7	2014-06-11	85.833 mi
Registration #8	2015-06-15	104.515 mi
Registration #9	2016-06-15	123.200 mi
Registration #10	2017-06-15	141.885 mi
Registration #11	2018-06-15	160.570 mi
Registration #12	2019-06-15	179.255 mi
Registration #13	2020-06-15	197.940 mi
Registration #14	2021-06-15	216.625 mi
Registration #15	2022-06-15	235.310 mi
Registration #16	2023-06-15	254.000 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1667 mm
Height	1521 mm
Length	3850 mm
Wheel base	2460 mm
Max. allowed weight	1597 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6F3239543