





General information

| Make | VOLKSWAGEN |
|---------------------|--------------------|
| Model | GOLF MATCH TSI EVO |
| Colour | White |
| Year of manufacture | 2019 |
| Top speed | 130 mph |
| 0 - 100 km/h | 9.1 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 96 kW / 131 HP / 128 BHP |
|-------------------------|--------------------------|
| Max. torque | 200 Nm at 1.400 rpm |
| Engine capacity | 1.498 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 36.2 mpg |
| Consumption extra urban | 57.4 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 113 g/km |
| CO2 label | С |







Internet history

Entry 1

Date

Pictures

2022-07-13

45

Listing price

View report









source: cargurus.co.uk



MOT history

| MOT expiry date | 2025-03-13 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 5 |
| Total items failed | 0 |

| MOT #3 | 2024-03-09 11:10 |
|---|------------------|
| MOT test number | 144818932273 |
| Result | Passed |
| Next expiry date | 2025-03-13 |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #2 | 2023-03-14 14:52 |
|-----------------|------------------|
| MOT test number | 978028110903 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2022-03-09 13:53 |

| MOT test number | 417786909663 |
|------------------------------------|--------------|
| Result | ✓ Passed |
| Advice Nearside Front Nail in tyre | |



Tax & MOT check

| ✓ Taxed Tax due: 1 August 2024 | ✓ MOT Expires: 13 March 2025 |
|---|---------------------------------------|
| Tax status | Valid until 1 August |
| Days left | 95 |
| MOT expiry date | 13 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E CAT ON |
| Date | * |
| Category | AMP |
| Туре | |

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10 700 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|--|-------------|
| ********* | |
| | |
| | |
| ********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| | |
| Rumber of plates | , |
| Rumber of plates Carrent registration | |
| Rumber of plates Carrent registration Fals since | |
| Rumber of protes Current registration Current registration | |
| Rumber of plates Carrent registration Fate since Fate since Fate since | 1000-20-20 |





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| In miles |
|-----------------|
| 5 |
| 2019-03-14 |
| 2024-03-09 |
| <u>See info</u> |
| |



| Registration #1 | 2019-03-14 | 18 mi |
|-----------------|------------|------------|
| Registration #2 | 2022-03-09 | 14.491 mi |
| Registration #3 | | 11.777 esi |
| Registration #4 | | 11.777 est |
| Registration #5 | | 11.777 mi |

More info >





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 94% |
| Children | 89% |
| Pedestrian | 65% |
| Safety systems | 71% |
| Overall rating | 85% |
| Video | see crash video |



| Dimensions & weight | |
|------------------------|---------|
| Width | 2027 mm |
| Height | 1492 mm |
| Length | 4258 mm |
| Wheel base | 2620 mm |
| Kerb weight | 1215 kg |
| Additional information | |
| Fuel tank capacity | 50 |

| Fuel tank capacity | 50 l |
|--------------------|------------|
| Number of axles | 2 |
| Engine number | DACA208870 |