



Mercedes-Benz

FD60WWF


report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	ML ML300 CDI BLUEEFFICIENCY SPORT
Colour	Grey
Year of manufacture	2011
Top speed	130 mph
0 - 100 km/h	8.7 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	150 kW / 204 HP / 204 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	38.2 mpg
Consumption combined	32.5 mpg
CO2 emission	240 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-06-26
Pictures	35
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-26
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	33
Total items failed	2

MOT #18	2023-12-27 09:53
MOT test number	179350120398
Result	✓ Passed
Next expiry date	2024-12-26

MOT #17	2023-07-07 11:28
MOT test number	856648640434
Result	✓ Passed

MOT #16	2023-07-05 13:09
MOT test number	111206286481
Result	✗ Failed

MAJOR Offside Rear Brake pipe excessively corroded front to rear pipes (1.1.11 (c))

MAJOR Nearside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

MAJOR Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MAJOR Nearside Front Inner Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #15** 2022-06-24 15:25**MOT test number** 142357053284**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #14** 2022-06-24 12:14**MOT test number** 370672811344**Result** ✗ Failed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #13** 2021-07-08 15:00**MOT test number** 616443371234**Result** ✓ Passed**MOT #12** 2021-07-08 09:15**MOT test number** 565174886055**Result** ✗ Failed**DANGEROUS** Central Exhaust silencer likely to become detached (8.1.1 (b) (ii))**DANGEROUS** Front Exhaust silencer likely to become detached (8.1.1 (b) (ii))**MOT #11** 2020-09-05 14:00**MOT test number** 796683357134**Result** ✓ Passed

**MOT #10**

2019-08-02 13:07

MOT test number

642002476748

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front height linkage siezed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2019-08-02 11:20

MOT test number

359079243192

Result

✗ Failed

MAJOR Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Offside Rear Brake pipe excessively corroded to flexi (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive gearbox pan area (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front height linkage siezed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8**

2018-08-01 14:19

MOT test number

933637363180

Result

✓ Passed

**MOT #7** 2018-08-01 12:01**MOT test number** 560306474175**Result** ✗ Failed**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #6** 2017-07-28 12:48**MOT test number** 991391418304**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-08-03 15:18**MOT test number** 345522449541**Result** ✓ Passed**Advice** Engine covers and under-trays fitted obscuring some components**MOT #4** 2016-08-01 14:08**MOT test number** 297974187451**Result** ✗ Failed**Advice** Engine cover and under trays fitted to vehicle**Fail** Brake pipe leaking front to rear (3.6.A.1)**Fail** Brake pipe excessively corroded front to rear (3.6.B.2c)**MOT #3** 2015-10-01 12:35**MOT test number** 171740818771**Result** ✓ Passed



MOT #2	2014-10-14 12:25
MOT test number	549007484287
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #1	2013-09-23 16:33
MOT test number	555006863215
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
31 January 2024

✓

MOT

Expires:
26 December 2024

Tax status	Expired at 31 January 2024
Days left	90 days too late
MOT expiry date	26 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 FD60WWF
Plate since	2024-03-29
Current registration	 FD60WWF
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-01-28
Last registration	2023-12-27
Complete history	See info



Registration #1	2011-01-28	26 mi
Registration #2	2013-09-23	32.856 mi
Registration #3	2014-10-14	48.321 mi
Registration #4	2015-10-01	60.941 mi
Registration #5	2016-08-01	69.010 mi
Registration #6	2016-08-03	69.026 mi
Registration #7	2017-07-28	84.126 mi
Registration #8	2018-08-01	96.982 mi
Registration #9	2018-08-01	96.982 mi
Registration #10	2019-08-02	107.362 mi
Registration #11	2019-08-02	107.362 mi
Registration #12	2019-08-02	107.362 mi
Registration #13	2019-08-02	107.362 mi
Registration #14	2019-08-02	107.362 mi
Registration #15	2019-08-02	107.362 mi
Registration #16	2019-08-02	107.362 mi
Registration #17	2019-08-02	107.362 mi
Registration #18	2019-08-02	107.362 mi
Registration #19	2019-08-02	107.362 mi
Registration #20	2019-08-02	107.362 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1911 mm
Height	1815 mm
Length	4781 mm
Wheel base	2915 mm
Kerb weight	2185 kg
Max. allowed weight	2830 kg

Additional information

Fuel tank capacity	95 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	64282041101600