



DWI4JCW

report date: 2024-03-29

General information

Make	MINI
Model	JOHN COOPER WORKS COOPER S
Colour	Grey
Year of manufacture	2014
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history


Entry 4

Date	2023-03-22
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 3


Date	2023-02-21
Pictures	50
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2023-02-21
Pictures	20
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-10-21
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-04
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	16
Total items failed	6

MOT #12	2024-04-03 13:54
MOT test number	438955158138
Result	✓ Passed
Next expiry date	2025-04-04
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11	2024-04-03 13:54
MOT test number	299325774767
Result	✗ Failed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10	2023-04-05 15:17
MOT test number	367467837050
Result	✓ Passed

MOT #9	2022-03-04 12:24
MOT test number	983586995884
Result	✓ Passed

**MOT #8** 2022-03-03 12:21**MOT test number** 439271655312**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases front joint (6.1.2 (a))**Advice** Nearside Rear Tyre slightly damaged sidewall (5.2.3 (d) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2021-01-06 15:29**MOT test number** 712450117765**Result** ✓ Passed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2021-01-06 09:37**MOT test number** 456768961275**Result** ✗ Failed**Fail** Nearside Front Inner Road wheel fractured (5.2.2 (a))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #5** 2020-02-03 09:13**MOT test number** 538121399104**Result** ✓ Passed**Advice** Engine covers and undertrays fitted

**MOT #4** 2019-05-08 14:33**MOT test number** 913180004367**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge excessively worn (5.2.3 (e))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing Outer sidewall has some large splits (5.2.3 (d) (ii))**MOT #3** 2019-05-08 09:40**MOT test number** 421092220202**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge excessively worn (5.2.3 (e))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing Outer sidewall has some large splits (5.2.3 (d) (ii))**Fail** Nearside Front Windscreen washer not working (3.5 (a))**MOT #2** 2018-05-24 08:29**MOT test number** 197020053025**Result** ✓ Passed**MOT #1** 2017-02-25 11:01**MOT test number** 275584503490**Result** ✓ Passed**Advice** Nearside Rear near side rear distorted out shape



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
4 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2014-03-08
Last registration	2024-04-03
Complete history	See info



Registration #1	2014-03-08	6 mi
Registration #2	2017-02-25	29.113 mi
Registration #3	2018-05-24	33.575 mi
Registration #4	2019-05-08	37.666 mi
Registration #5	2019-05-08	37.666 mi
Registration #6	2020-02-03	39.259 mi
Registration #7	2021-01-06	43.533 mi
Registration #8	2021-01-06	43.533 mi
Registration #9	2022-05-20	55.277 mi
Registration #10	2022-05-20	55.277 mi
Registration #11	2022-05-20	55.277 mi
Registration #12	2022-05-20	55.277 mi
Registration #13	2022-05-20	55.277 mi
Registration #14	2022-05-20	55.277 mi
Registration #15	2022-05-20	55.277 mi
Registration #16	2022-05-20	55.277 mi
Registration #17	2022-05-20	55.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1335 kg
Max. allowed weight	1845 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	A563J843