




report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER TD XS STATION WAGON
Colour	White
Year of manufacture	2015
Top speed	90 mph
0 - 100 km/h	15.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 kW / 123 HP / 122 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	20.8 mpg
Consumption extra urban	29.1 mpg
Consumption combined	25.5 mpg
CO2 emission	295 g/km
CO2 label	M





Internet history

Entry 2

Date	2022-01-30
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk

Entry 1

Date	2021-09-15
Pictures	0
Listing price	<a href="#">View report</a>

source: heycar.co.uk



## MOT history

MOT expiry date	2025-04-15
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	6
Total items failed	5

MOT #13	2024-04-16 09:43
MOT test number	135673136100
Result	✓ Passed
Next expiry date	2025-04-15

MOT #12	2024-04-05 10:03
MOT test number	677865862973
Result	✗ Failed
Fail	Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))

MOT #11	2023-03-14 14:35
MOT test number	691828781574
Result	✓ Passed

MOT #10	2023-03-09 16:22
MOT test number	716188077863
Result	✗ Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #9	2022-03-17 15:55
MOT test number	670502936170
Result	✓ Passed

**MOT #8** 2022-03-17 08:01**MOT test number** 624430244443**Result** ✗ Failed**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Rear Lower Shock absorbers has a slightly worn bush Both (5.3.2 (c))**MOT #7** 2021-09-20 15:49**MOT test number** 662394484583**Result** ✓ Passed**MOT #6** 2021-05-19 12:01**MOT test number** 413198999025**Result** ✓ Passed**MOT #5** 2020-05-12 11:28**MOT test number** 497613213101**Result** ✓ Passed**MOT #4** 2020-05-06 10:07**MOT test number** 984639010574**Result** ✗ Failed**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



MOT #3	2019-03-20 11:14
MOT test number	501692332061
Result	✓ Passed
MOT #2	2018-03-14 12:36
MOT test number	367187211132
Result	✓ Passed
MOT #1	2018-03-14 11:45
MOT test number	465700121037
Result	✗ Failed
Fail	Offside Rear Lower Shock absorber has an excessively worn bush (2.7.4)
Advice	Nearside Rear Shock absorber has a slightly worn bush (2.7.4)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
15 April 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	15 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-




Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2015-03-25
Last registration	2024-04-16
Complete history	<a href="#">See info</a>



Registration #1	2015-03-25	29 mi
Registration #2	2018-03-14	34.548 mi
Registration #3	2018-03-14	34.548 mi
Registration #4	2019-03-20	45.590 mi
Registration #5	2020-05-06	52.246 mi
Registration #6	2020-05-12	52.247 mi
Registration #7	2021-05-19	55.991 mi
Registration #8	2022-05-20	59.277 mi
Registration #9	2023-05-20	62.577 mi
Registration #10	2024-05-20	65.877 mi
Registration #11	2025-05-20	69.177 mi
Registration #12	2026-05-20	72.477 mi
Registration #13	2027-05-20	75.777 mi
Registration #14	2028-05-20	79.077 mi
Registration #15	2029-05-20	82.377 mi
Registration #16	2030-05-20	85.677 mi

More info >



Dimensions & weight

Width	1992 mm
Height	2181 mm
Length	4785 mm
Wheel base	2794 mm
Kerb weight	2125 kg
Max. allowed weight	3050 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	7
Number of axles	2
Engine number	141206102044DT224