



Mercedes-Benz



493AAT


report date: 2024-03-29

General information

Make	MERCEDES
Model	S-Class S320 CDI
Colour	Black
Year of manufacture	2007
Top speed	149 mph
0 - 60 mph	7.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.0 mpg
CO2 emission	225 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-11-05
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-06
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	40
Total items failed	14

MOT #20	2023-12-01 10:40
MOT test number	522881147075
Result	✓ Passed
Next expiry date	2024-12-06
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #19	2023-12-01 10:30
MOT test number	319928368768
Result	✗ Failed
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #18	2022-12-07 17:37
MOT test number	489965515321
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge + Perishing (5.2.3 (e))

**MOT #17**

2022-11-24 14:09

MOT test number

166652556275

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge + Perishing (5.2.3 (e))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #16**

2021-11-23 14:28

MOT test number

172284001052

Result**✓ Passed****Advice** Front Brake pad(s) wearing thin very low (1.1.13 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Service light illuminated suggesting vehicle service overdue**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))**Advice** Nearside Non obligatory mirror damaged Indicator cover damaged**Advice** Offside Rear Light unit slightly damaged along bottom**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15**

2021-11-23 14:28

MOT test number

232022283600

Result**✗ Failed**

- Advice** Service light illuminated suggesting vehicle service overdue
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Front Windscreen washer not working (3.5 (a))
- Advice** Nearside Non obligatory mirror damaged Indicator cover damaged
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Light unit slightly damaged along bottom
- Advice** Front Brake pad(s) wearing thin very low (1.1.13 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #14

2021-11-05 12:32

MOT test number

600018730131

Result**✗ Failed**

- Fail** Front Brake disc significantly and obviously worn Both (1.1.14 (a) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick Both (1.1.13 (a) (ii))
- Fail** Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
- Fail** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #13** 2020-06-12 13:36**MOT test number** 880104029288**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-11-06 13:22**MOT test number** 133674244990**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2017-11-15 09:44**MOT test number** 453509903314**Result** ✓ Passed**MOT #10** 2017-11-13 15:18**MOT test number** 390190367471**Result** ✗ Failed**Fail** Nearside Front Inner Tyre has ply or cords exposed (4.1.D.1b)**MOT #9** 2015-11-19 12:06**MOT test number** 671905954341**Result** ✓ Passed**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2014-03-25 12:35**MOT test number** 676714184071**Result** ✓ Passed

**MOT #7** 2014-03-24 15:59**MOT test number** 169263184062**Result** ✗ Failed**Fail** Offside Rear Tyre has had the tread recut (4.1.D.1c)**Notice** Nail in nearside rear tyre**MOT #6** 2013-02-19 14:15**MOT test number** 257550253008**Result** ✓ Passed**Notice** Nail in nearside front tyre**MOT #5** 2013-02-19 13:09**MOT test number** 527400453015**Result** ✗ Failed**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Nail in nearside front tyre**MOT #4** 2012-08-01 09:12**MOT test number** 587024912253**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-08-01 09:12**MOT test number** 507924312234**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)



MOT #2	2011-03-22 10:20
MOT test number	696571881045
Result	✓ Passed
MOT #1	2009-12-22 15:03
MOT test number	223976359325
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
6 December 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	6 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-01-10
Last registration	2023-12-01
Complete history	See info



Registration #1	2007-01-10	15 mi
Registration #2	2009-12-22	28.701 mi
Registration #3	2011-03-22	35.664 mi
Registration #4	2012-08-01	44.235 mi
Registration #5	2013-02-19	46.589 mi
Registration #6	2013-02-19	46.589 mi
Registration #7	2014-03-24	55.268 mi
Registration #8	2014-03-25	55.271 mi
Registration #9	2015-11-19	61.214 mi
Registration #10	2017-11-13	67.171 mi
Registration #11	2017-11-15	67.173 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi
Registration #19	2019-05-29	75.277 mi
Registration #20	2019-05-29	75.277 mi
Registration #21	2019-05-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5076 mm
Wheel base	3035 mm
Kerb weight	1965 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64293040497268