





report date: 2024-03-29

General information

Make	FORD
Model	FOCUS C-MAX ZETEC 100
Colour	Blue
Year of manufacture	2008
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 2

Date 2021-07-08

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-07-07
Pictures	20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2024-06-19
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	29
Total items failed	9

MOT #17	2023-06-20 13:53
MOT test number	776622216524
Result	✓ Passed
Next expiry date	2024-06-19
Minor Nearside Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))	
Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	

MOT #16	2023-06-20 13:33	
MOT test number	764556451351	
Result	🗙 Failed	
Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))		
Fail Front Headlamp lens seriously defective both lenses hazy/deteriorated (4.1.1 (b) (ii))		
Minor Nearside Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))		
Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))		

MOT #15	2022-06-20 15:43
MOT test number	233887255153
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view cracked (3.2 (a) (i))	ı

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #14

MOT test number

309621682904

Result

Fail Headlamp lens seriously defective both lenses excessively deteriorated/hazy (4.1.1 (b) (ii))

Fail Nearside Headlamp aim projected beam image is obviously incorrect bulb not seated correctly (4.1.2 (c))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #13

MOT test number

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (iii))

MOT test number

Result

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT test number

Result

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10 2020-05-28 10:10 **MOT** test number 272130072602 Result × Failed Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) Fail Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i)) **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #9	2019-06-04 08:23
MOT test number	447812031028
Result	✓ Passed
Advice Nearside Front Road whee	I slightly distorted (5.2.2 (c) (i))
Advice Offside Rear Brake hose h	as slight corrosion to ferrule (1.1.12 (f) (i))

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #8		2018-05-29 09:04
MOT test	number	394681281086
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2017-05-31 09:22
MOT test number	369671278371
Result	✓ Passed
Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	

MOT #6	2016-05-26 12:00
MOT test number	259797086568
Result	✓ Passed
MOT #5	2015-05-26 11:18
MOT test number	805586145181
Result	✓ Passed
MOT #4	2014-05-16 12:30
MOT test number	278656034164
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #3		2013-06-01 11:58
MOT test n	number	285662753442
Result		✓ Passed
Notice	O/s/f tyre worn on inner edge	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #2		2012-05-24 12:14
MOT test	number	257455342106
Result		✓ Passed
MOT #1		2011-06-10 09:29
MOT test	number	865331261100
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	19 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



RF08FYH report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

_	
Owner	hictory
OWITE	HIISLOLY

,		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ave?
PROFESSOR		
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NEZ	
Flate since		
	More info	>

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-07-30
Last registration	2023-06-20
Complete history	See info



Registration #1	2008-07-30	28 mi
Registration #2	2011-06-10	29.888 mi
Registration #3	2012-05-24	34.230 mi
Registration #4	2013-06-01	38.740 mi
Registration #5	2014-05-16	42.432 mi
Registration #6	2015-05-26	46.611 mi
Registration #7	2016-05-26	51.104 mi
Registration #8	2017-05-31	55.216 mi
Registration #9	2018-05-29	59.539 mi
Registration #10	2019-06-04	64.202 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		n.m.

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/1

Number of axles 2
Engine number 8K23159