





report date: 2024-03-28

### General information

Make	CITROEN
Model	RELAY 35 L2 HDI
Colour	White
Year of manufacture	2014
Top speed	96 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 сс
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	32.5 mpg
CO2 emission	229 g/km
CO2 label	L



CarCheck.co.uk page 1/12



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-09-07
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	22
Total items failed	18

MOT #11	2023-08-18 09:40
MOT test number	193072670573
Result	<b>✓</b> Passed
Next expiry date	2024-09-07

MOT #10	2022-09-07 08:33
MOT test number	522390368730
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #9	2021-09-08 10:15
MOT test number	520091693513
Result	✓ Passed

	2021-09-07 14:30
MOT test number	983103490342
Result	<b>×</b> Failed
Fail Service brake efficiency less than 50% of the required value (1.2.2 (a) (ii))  Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

CarCheck.co.uk page 2/12



report date: 2024-03-28

**MOT #7** 2020-10-20 15:23 **MOT** test number 466571603752 ✓ Passed Result **Advice** Both hand brake cables worn **Advice** Nearside Play in steering rack inner joint(s) **Advice** Air filter housing insecure Damage to both side repeaters Advice Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT** #6 2020-10-19 14:37 399627101224 **MOT test number** Result ★ Failed Fail Windscreen washer provides insufficient washer liquid (3.5 (a)) **Advice** Air filter housing insecure Offside Rear Direction indicator not working (4.4.1 (a) (ii)) Fail **Advice** Damage to both side repeaters Fail Nearside Front Lower Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) **Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) **Advice** Both hand brake cables worn Fail Nearside Side repeater not working (4.4.1 (a) (ii)) **Advice** Nearside Play in steering rack inner joint(s) Fail Nearside Rear Tyre fouling a part of the vehicle inner wheel well damaged (5.2.3 (f)) Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Advice F/n/s tyre worn on outer edge

Advice Uneven wear to r/n/s tyre inner edge

**MOT #4** 2019-04-11 14:53 **MOT** test number 734354735559 Result **X** Failed Fail Offside Headlamp aim too low (4.1.2 (a)) **Advice** F/o/s upper strut mounting worn Advice Offside Rear Nail in tyre Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i)) Fail Advice F/n/s tyre worn on outer edge **Advice** Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i)) Fail Offside Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail Nearside Headlamp aim too high (4.1.2 (a)) **Advice** Uneven wear to r/n/s tyre inner edge Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #3

MOT test number

683714204036

Result

Advice Front Shock absorber has a light misting of oil both (2.7.3)

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2 2018-04-24 11:34 **MOT test number** 278121223198 Result × Failed Fail Offside Registration plate lamp not working (1.1.C.1d) Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Advice Front Shock absorber has a light misting of oil both (2.7.3) Fail Nearside Headlamp aim too high (1.8) Nearside Side repeater incorrect colour (1.4.A.2f) Fail Fail Offside Headlamp not working on dipped beam (1.7.5a)

 MOT #1
 2017-01-16 12:22

 MOT test number
 359166971788

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



PK63YXX report date: 2024-03-28

Tax & MOT check





**Expires:** 7 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	7 September 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



PK63YXX report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	I-!
OWNER	nistory
	11136017

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROE have? Check it in the premium report and see all owner registrations. Download the full report
--

CarCheck.co.uk page 9/12



PK63YXX report date: 2024-03-28

### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-01-24
Last registration	2023-08-18
Complete history	See info



Registration #1	2014-01-24	18 mi
Registration #2	2017-01-16	56.271 mi
Registration #3	2018-04-24	70.843 mi
Registration #4	2018-04-24	70.843 mi
Registration #5	2019-04-11	84.549 mi
Registration #6	2019-04-12	84.549 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		n.m.

More info >

CarCheck.co.uk page 11/12



PK63YXX report date: 2024-03-28

# Safety ratings

NCAP rating	****
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



# Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Number of axles	2
Engine number	TRJA0767555

CarCheck.co.uk page 12/12