



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF S
Colour	Blue
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	144 g/km
CO2 label	F



**MOT history**

MOT expiry date	2021-12-30
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	34
Total items failed	6

MOT #12	2020-12-31 15:00
----------------	------------------

MOT test number	747912352600
------------------------	--------------

Result	✓ Passed
---------------	----------

Next expiry date	2021-12-30
-------------------------	------------

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge WORN ON INNER EDGE (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge WORN ON INNER EDGE (5.2.3 (e))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge WORN ON INNER EDGE (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge WORN ON INNER EDGE (5.2.3 (e))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11** 2020-12-29 17:29**MOT test number** 234343619085**Result** ✗ Failed**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge WORN ON INNER EDGE (5.2.3 (e))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge WORN ON INNER EDGE (5.2.3 (e))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge WORN ON INNER EDGE (5.2.3 (e))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge WORN ON INNER EDGE (5.2.3 (e))**MOT #10** 2019-08-19 17:34**MOT test number** 793778644009**Result** ✓ Passed**MOT #9** 2018-08-09 08:45**MOT test number** 227413817276**Result** ✓ Passed

**MOT #8** 2017-07-25 16:14**MOT test number** 699678906633**Result** ✓ Passed

- Advice** Engine oil level very low
- Advice** Service reminder on dash
- Advice** Offside Front under tray insecure
- Advice** All tyres very low on pressure
- Advice** Nearside Front under tray insecure

MOT #7 2017-07-25 14:17**MOT test number** 941217956516**Result** ✗ Failed

- Advice** Nearside Front under tray insecure
- Advice** Engine oil level very low
- Advice** Service reminder on dash
- Advice** Offside Front tyre inside close to cords
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Offside Front under tray insecure
- Advice** All tyres very low on pressure

MOT #6 2016-06-07 08:01**MOT test number** 177653660517**Result** ✓ Passed

- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #5** 2015-07-25 10:25**MOT test number** 285796305263**Result** ✓ Passed**Advice** Nearside Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #4** 2015-07-18 12:29**MOT test number** 897679095172**Result** ✗ Failed**Fail** Nearside Rear rear brake binding (3.7.B.1)**Fail** Nearside Front Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear rear brake binding (3.7.B.1)**Advice** Nearside Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-06-09 15:22**MOT test number** 676170464159**Result** ✓ Passed**MOT #2** 2013-07-09 15:33**MOT test number** 709470693164**Result** ✓ Passed**MOT #1** 2012-07-13 10:50**MOT test number** 868165492151**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
30 April 2021

✕
MOT

Expired:
30 December 2021

Tax status	Expired at 30 April 2021
Days left	1094 days too late
MOT expiry date	30 December 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	VN09DLD
Plate since	2019-06-29
Current registration	VN09DLD
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-06-29
Last registration	2020-12-31
Complete history	See info



Registration #1	2009-06-29	10 mi
Registration #2	2012-07-13	27.973 mi
Registration #3	2013-07-09	32.932 mi
Registration #4	2014-06-09	42.751 mi
Registration #5	2015-07-18	55.411 mi
Registration #6	2015-07-25	55.597 mi
Registration #7	2016-06-07	63.233 mi
Registration #8	2016-06-07	63.233 mi
Registration #9	2016-06-07	63.233 mi
Registration #10	2016-06-07	63.233 mi
Registration #11	2016-06-07	63.233 mi
Registration #12	2016-06-07	63.233 mi
Registration #13	2016-06-07	63.233 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1142 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAX 206347