





report date: 2024-03-29

#### General information

Make	HYUNDAI
Model	I30 CRDI SE BLUE DRIVE
Colour	Black
Year of manufacture	2016
Top speed	117 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	83.1 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



### Internet history


#### Entry 1

Date 2021-05-23

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



# MOT history

MOT expiry date	2024-08-09
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	9
Total items failed	9

MOT #7		2023-08-10 12:28
MOT test	number	944219699706
Result		✓ Passed
Next expi	ry date	2024-08-09
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	))

MOT #6	2023-08-10 09:54
NOT test number	597187127289
Result	<b>×</b> Failed
Fail Offside Front Headlamp aim too high (4.1.2 (a))	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.	.1.14 (a) (ii))
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Nearside Front Headlamp aim too high (4.1.2 (a))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



MOT #5 2022-08-08 10:44

**MOT test number** 900208535370

Result X Failed

Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #4 2021-08-18 13:22

**MOT test number** 652855665606

Result \square Passed

MOT #3 2021-08-17 16:11

**MOT test number** 792000446804

Result X Failed

Fail Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Front Service brake excessively fluctuating (1.2.1 (e))

MOT #2 2020-10-26 14:34

MOT test number 612579852656

**Result** ✓ Passed

**MOT #1** 2019-04-17 13:06

MOT test number 709028328111

Advice Nearside Rear Brake pad(s) wearing thin Brake tested ok (1.1.13 (a) (ii))

Advice Nearside Integral body structure is deformed but structural rigidity is not significantly reduced Sill

damaged (6.1.1 (a) (i))

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	9 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



## Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK NY
Plate since	
	More info

CarCheck.co.uk page 8/11



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-04-21
Last registration	2023-08-10
Complete history	See info



Registration #1	2016-04-21	19 mi
Registration #2	2019-04-17	42.351 mi
Registration #3	2020-10-26	59.603 mi
Registration #4		11.777 es
Registration #5	2021-08-17	63.571 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1429 kg
Max. allowed weight	1920 kg

# Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

**Engine number** D4FBGZ136218