



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC LL29 LWB L/C CRC 115 DCI
Colour	Red
Year of manufacture	2007
Top speed	99 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.4 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 2


Date	2023-06-17
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-25
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-26
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	42
Total items failed	10

MOT #17	2023-06-27 10:41
MOT test number	177091249086
Result	✓ Passed
Next expiry date	2024-06-26

MOT #16	2022-10-17 15:20
MOT test number	669697083103
Result	✓ Passed
Advice	Offside Rear Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge perished also (5.2.3 (e))
Advice	Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
Advice	Both front jacking points corroded
Advice	Oil weep

**MOT #15**

2021-10-07 12:52

MOT test number

701749859318

Result

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Both rear tyres perished
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material Both front to rear (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14

2020-10-21 14:43

MOT test number

143938258867

Result

✓ Passed

- Advice** Nearside Rear Service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.2.2 (a) (i))

MOT #13

2019-10-19 10:13

MOT test number

200199154531

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Inside door handle insecure but still functioning

**MOT #12** 2019-10-16 09:38**MOT test number** 438929031162**Result** ✗ Failed**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Front Inside door handle insecure but still functioning**Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #11** 2018-10-11 08:32**MOT test number** 575980759238**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material front to rear leading to offside rear flexi hose (1.1.11 (c))**Advice** Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2017-10-18 15:05**MOT test number** 723393971383**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt slight play in ball joint (2.4.G.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Brake pipe slightly corroded front to rear leading to offside rear flexi hose (3.6.B.2c)**Advice** Oil leak

**MOT #9** 2017-10-13 13:52**MOT test number** 886570237640**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Brake pipe slightly corroded front to rear leading to offside rear flexi hose (3.6.B.2c)**Advice** Oil leak**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt slight play in ball joint (2.4.G.2)**MOT #8** 2016-10-22 08:36**MOT test number** 551214300793**Result** ✓ Passed**MOT #7** 2015-10-23 11:21**MOT test number** 208983620431**Result** ✓ Passed**Advice** Power steering fluid level low, but not below minimum (2.3.1)**Advice** Play in steering rack inner joints**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2015-10-23 11:21**MOT test number** 488679420026**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Play in steering rack inner joints**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Power steering fluid level low, but not below minimum (2.3.1)**MOT #5** 2014-10-24 10:25**MOT test number** 949207194249**Result** ✓ Passed**MOT #4** 2013-09-07 09:42**MOT test number** 919850953298**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Play in steering rack inner joint(s)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**Notice** Oil leak**MOT #3** 2012-09-11 12:57**MOT test number** 495915152209**Result** ✓ Passed



MOT #2	2011-12-01 11:37
MOT test number	368015131329
Result	✓ Passed

MOT #1	2010-12-29 14:26
MOT test number	481593360382
Result	✓ Passed

Notice Slight spongyness to brake pedal but performance on road test seems OK



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
26 June 2024

Tax status	Valid until 1 August
-------------------	----------------------

Days left	94
------------------	----

MOT expiry date	26 June 2024
------------------------	--------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	EF57LXS
Plate since	2024-03-29
Current registration	EF57LXS
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-12-28
Last registration	2023-06-27
Complete history	See info



Registration #1	2007-12-28	9 mi
Registration #2	2010-12-29	37.909 mi
Registration #3	2011-12-01	40.494 mi
Registration #4	2012-09-11	41.157 mi
Registration #5	2013-09-07	49.012 mi
Registration #6	2014-10-24	59.227 mi
Registration #7	2015-10-23	69.218 mi
Registration #8	2015-10-23	69.218 mi
Registration #9	2016-10-22	79.468 mi
Registration #10	2017-10-13	88.670 mi
Registration #11	2018-06-20	95.377 mi
Registration #12	2019-06-20	101.377 mi
Registration #13	2020-06-20	107.377 mi
Registration #14	2021-06-20	113.377 mi
Registration #15	2022-06-20	119.377 mi
Registration #16	2023-06-20	125.377 mi
Registration #17	2024-06-20	131.377 mi
Registration #18	2025-06-20	137.377 mi
Registration #19	2026-06-20	143.377 mi
Registration #20	2027-06-20	149.377 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2232 mm
Height	1944 mm
Length	5182 mm
Kerb weight	1886 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	6
Engine number	C159106