



report date: 2024-03-29

General information

Make	VOLVO
Model	S80 D5 SE LUX
Colour	Grey
Year of manufacture	2007
Top speed	140 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-11
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-28
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	25
Total items failed	14

MOT #21	2024-01-29 16:09
MOT test number	984630856508
Result	✓ Passed
Next expiry date	2025-01-28

MOT #20	2024-01-22 10:41
MOT test number	366610206907
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #19	2023-01-24 16:13
MOT test number	200426978259
Result	✓ Passed

**MOT #18**

2023-01-20 12:38

MOT test number

286574260916

Result**✗ Failed****Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #17**

2022-01-22 10:49

MOT test number

873175775536

Result**✓ Passed****Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement N/S & O/S Trailing arm bushes (5.3.4 (a) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Under-trays fitted front & rear**Advice** Rear Tyre worn close to legal limit/worn on edge N/S & O/S Worn/out of shape inner edge (5.2.3 (e))**MOT #16**

2022-01-21 09:43

MOT test number

630475264322

Result**✗ Failed****Advice** Under-trays fitted front & rear**Advice** Rear Tyre worn close to legal limit/worn on edge N/S & O/S Worn/out of shape inner edge (5.2.3 (e))**Fail** Nearside Front Position lamp not working Side Marker (4.2.1 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement N/S & O/S Trailing arm bushes (5.3.4 (a) (i))

**MOT #15** 2020-12-17 09:20**MOT test number** 258075306059**Result** ✓ Passed**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #14** 2019-12-11 09:37**MOT test number** 124303689602**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13** 2019-12-11 09:37**MOT test number** 988377309558**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2019-01-04 09:06**MOT test number** 586411686883**Result** ✓ Passed**MOT #11** 2017-12-06 13:11**MOT test number** 665061818827**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Rear Brake pad(s) wearing thin both (3.5.1g)

**MOT #10** 2017-12-05 16:20**MOT test number** 185965126911**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin both (3.5.1g)**Fail** Nearside Front Steering rack gaiter insecure (2.2.D.2d)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**MOT #9** 2016-12-02 11:02**MOT test number** 709150033938**Result** ✓ Passed**MOT #8** 2015-12-08 09:59**MOT test number** 254066675290**Result** ✓ Passed**MOT #7** 2015-12-07 15:58**MOT test number** 494462976687**Result** ✗ Failed**Fail** Nearside Steering rack gaiter insecure (2.2.D.2d)**MOT #6** 2014-09-01 10:40**MOT test number** 727734144269**Result** ✓ Passed**Notice** 225/50/ZR17/98W. OF 3 OR 5 NR 7 NF 3mm.

**MOT #5** 2013-08-30 12:12**MOT test number** 369842743455**Result** ✓ Passed**Notice** Exhaust system corroded**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2012-07-14 12:14**MOT test number** 106586092159**Result** ✓ Passed**MOT #3** 2012-07-13 12:00**MOT test number** 257455892407**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** 225/50/R17/98W. OF 1 OR 5 NR 6 NF 1mm.**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2011-07-12 14:31**MOT test number** 159953591186**Result** ✓ Passed**MOT #1** 2010-11-30 13:49**MOT test number** 603914230338**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
28 January 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	28 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-12-07
Last registration	2024-01-29
Complete history	See info



Registration #1	2007-12-07	16 mi
Registration #2	2010-11-30	40.376 mi
Registration #3	2011-07-12	45.823 mi
Registration #4	2012-07-13	62.300 mi
Registration #5	2012-07-14	62.323 mi
Registration #6	2013-08-30	70.473 mi
Registration #7	2014-09-01	75.189 mi
Registration #8	2015-12-07	80.623 mi
Registration #9	2015-12-08	80.624 mi
Registration #10	2016-12-02	95.117 mi
Registration #11	2017-12-05	109.291 mi
Registration #12	2017-12-06	109.292 mi
Registration #13	2018-01-01	110.000 mi
Registration #14	2018-01-01	110.000 mi
Registration #15	2018-01-01	110.000 mi
Registration #16	2018-01-01	110.000 mi
Registration #17	2018-01-01	110.000 mi
Registration #18	2018-01-01	110.000 mi
Registration #19	2018-01-01	110.000 mi
Registration #20	2018-01-01	110.000 mi
Registration #21	2018-01-01	110.000 mi
Registration #22	2018-01-01	110.000 mi
Registration #23	2018-01-01	110.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1570 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	490903
---------------	--------