



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EASY
Colour	Grey
Year of manufacture	2014
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-11-02
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	16
Total items failed	10

MOT #13	2023-11-03 15:52
MOT test number	427374445336
Result	✓ Passed
Next expiry date	2024-11-02
Advice	Front Play in steering rack inner joint(s) both
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12	2023-11-03 09:25
MOT test number	546680717222
Result	✗ Failed
Fail	Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Front Play in steering rack inner joint(s) both
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #11** 2022-11-01 16:06**MOT test number** 335863501507**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10** 2022-10-31 12:55**MOT test number** 933750964150**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #9** 2021-11-03 12:23**MOT test number** 809402264720**Result** ✓ Passed**MOT #8** 2021-02-18 17:24**MOT test number** 506219813663**Result** ✓ Passed**MOT #7** 2020-05-22 09:11**MOT test number** 583791606289**Result** ✓ Passed

**MOT #6** 2019-06-10 13:22**MOT test number** 867938306950**Result** ✓ Passed**MOT #5** 2019-05-28 13:51**MOT test number** 923515905133**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #4** 2018-06-04 08:00**MOT test number** 234285636043**Result** ✓ Passed**MOT #3** 2018-06-01 15:27**MOT test number** 392715512027**Result** ✗ Failed**Advice** Offside Rear Position lamp has a product on the lens or light source but not adversely affecting light intensity slight crack in lens (4.2.3 (b) (ii))**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**MOT #2** 2017-06-09 13:08**MOT test number** 813437717423**Result** ✓ Passed**MOT #1** 2017-06-09 07:54**MOT test number** 776508301937**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
2 November 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	2 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-06-27
Last registration	2023-11-03
Complete history	<a href="#">See info</a>



Registration #1	2014-06-27	26 mi
Registration #2	2017-06-09	14.454 mi
Registration #3	2017-06-09	14.455 mi
Registration #4	2018-06-01	23.371 mi
Registration #5	2018-06-04	23.371 mi
Registration #6	2019-05-28	33.187 mi
Registration #7	2019-06-10	33.656 mi
Registration #8	2020-05-22	40.687 mi
Registration #9	2020-05-22	40.687 mi
Registration #10	2020-05-22	40.687 mi
Registration #11	2020-05-22	40.687 mi
Registration #12	2020-05-22	40.687 mi
Registration #13	2020-05-22	40.687 mi
Registration #14	2020-05-22	40.687 mi
Registration #15	2020-05-22	40.687 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	0798077