




report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI AIRDREAM DSPORT
Colour	Red
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-28
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	27
Total items failed	14

MOT #17	2024-03-08 11:40
MOT test number	653335217896
Result	✓ Passed
Next expiry date	2025-03-28
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))

MOT #16	2023-03-17 13:57
MOT test number	403836757094
Result	✓ Passed
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))

MOT #15	2023-03-16 11:53
MOT test number	318129739270
Result	✗ Failed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #14**

2022-03-23 17:06

MOT test number

418148433262

Result

✓ Passed

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13

2022-03-23 14:47

MOT test number

416257034903

Result

✗ Failed

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12

2021-03-29 13:40

MOT test number

975755796127

Result

✓ Passed

Advice

Front Registration plate slightly damaged

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2021-03-29 13:40

MOT test number

119576149391

Result**✗ Failed****Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Pass with rectification** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Registration plate slightly damaged**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10**

2020-09-04 11:21

MOT test number

276788225386

Result**✓ Passed****Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #9** 2020-09-04 09:15**MOT test number** 236822881503**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #8** 2019-09-25 08:02**MOT test number** 906539488187**Result** ✓ Passed**MOT #7** 2018-12-18 13:50**MOT test number** 203230930103**Result** ✓ Passed**MOT #6** 2018-12-18 10:54**MOT test number** 703032991545**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #5** 2017-07-18 09:35**MOT test number** 500219364422**Result** ✓ Passed**Advice** Items removed from driver's view prior to test air freshener

**MOT #4** 2017-07-18 09:35**MOT test number** 766212435244**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Advice** Items removed from driver's view prior to test air freshener**Pass with rectification** Offside Front Headlamp aim too low (1.8)**MOT #3** 2016-07-19 11:35**MOT test number** 909420104263**Result** ✓ Passed**MOT #2** 2016-07-18 13:53**MOT test number** 260663822964**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2015-10-22 11:17**MOT test number** 681804325773**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
28 March 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	28 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-11-23
Last registration	2024-03-08
Complete history	See info



Registration #1	2012-11-23	29 mi
Registration #2	2015-10-22	42.992 mi
Registration #3	2016-07-18	46.105 mi
Registration #4	2016-07-19	46.105 mi
Registration #5	2017-07-18	56.794 mi
Registration #6	2017-07-18	56.794 mi
Registration #7	2018-12-18	68.406 mi
Registration #8	2018-12-18	68.406 mi
Registration #9	2019-09-25	71.994 mi
Registration #10	2020-09-04	84.977 mi
Registration #11	2020-09-04	84.977 mi
Registration #12	2020-09-04	84.977 mi
Registration #13	2020-09-04	84.977 mi
Registration #14	2020-09-04	84.977 mi
Registration #15	2020-09-04	84.977 mi
Registration #16	2020-09-04	84.977 mi
Registration #17	2020-09-04	84.977 mi
Registration #18	2020-09-04	84.977 mi
Registration #19	2020-09-04	84.977 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBEF3023664