





report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE V6 SE
Colour	Silver
Year of manufacture	-
Top speed	135 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	244 Nm at 3.000 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	18.6 mpg
Consumption extra urban	36.7 mpg
Consumption combined	27.2 mpg



CarCheck.co.uk page 1/12



GY06LPU

report date: 2024-03-28

Internet history

Entry 2

Date 2021-10-23

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-10-21

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



GY06LPU

report date: 2024-03-28

MOT history

MOT #17 2022-02-04 15:16

MOT test number 969676838789

Result X Failed

Minor Offside Front Brake hose slightly chafed (1.1.12 (b) (i))

MAJOR Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

MAJOR Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Headlamp aim not tested (4.1.2 (b))

Advice Nearside Front brake binding excessively

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MAJOR Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MAJOR Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front brake binding excessively

MOT #16 2021-01-30 11:03

MOT test number 500450569949

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2021-01-30 11:03

MOT test number 850345669714

Result × Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Pass with rectification Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

CarCheck.co.uk page 3/12



✓ Passed

MOT #14 2020-01-21 11:43

MOT test number 398460007391

Result ✓ Passed

MOT #13 2020-01-21 11:43

MOT test number 537484962376

Result × Failed

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Pass with rectification Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #12 2019-01-26 12:32

MOT test number 613292459418

Result \rightarrow Passed

MOT #11 2018-01-12 11:25

MOT test number 899624662738

Result \sqrt{Passed}

Advice Engine management light on

Result

MOT #10 2017-01-13 17:25

MOT test number 742510588455

, 12523356.55

Advice Front brake discs worn/corroded(inner surfaces)

CarCheck.co.uk page 4/12



MOT #9 2017-01-13 09:39

MOT test number 330580097913

Result X Failed

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Nearside Front Seat belt locking mechanism does not secure or release (5.2.5a)

Advice Front brake discs worn/corroded(inner surfaces)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Nearside Stop lamp not working (1.2.1b)

MOT #8 2016-01-27 16:21

MOT test number 816400216534

MOT #7 2015-04-18 09:24

MOT test number 896348305158

Result ✓ Passed

MOT #6 2014-05-10 10:22

MOT test number 876640334140

Result ✓ Passed

MOT #5 2013-03-25 11:38

MOT test number 695374483018

Notice Wipers could be better

CarCheck.co.uk page 5/12



 MOT #4
 2012-03-19 11:52

 MOT test number
 589579972054

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Wipers could be better

MOT #3 2011-03-17 15:30

MOT test number 326136671067

Notice O/s wiper could be better

MOT #2 2010-03-23 11:48

MOT test number 342452080059

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2009-03-20 14:31

MOT test number 252079779071

CarCheck.co.uk page 6/12



GY06LPU

report date: 2024-03-28

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	OK SIN
Plate since	
Current registration	UK ZIS
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-25
Last registration	2022-02-04
Complete history	See info



Registration #1	2006-03-25	6 mi
Registration #2	2009-03-20	37.938 mi
Registration #3	2010-03-23	43.471 mi
Registration #4	2011-03-17	49.485 mi
Registration #5	2012-03-19	57.919 mi
Registration #6	2013-03-25	61.479 mi
Registration #7	2014-05-10	66.035 mi
Registration #8	2015-04-18	74.717 mi
Registration #9	2016-01-27	83.560 mi
Registration #10	2017-01-13	93.046 mi
Registration #11		9.79 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.79 es
Registration #18		11.777 es
Registration #19		D.777 es
Registration #20		n.m.

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
-------------	------

Video <u>see crash video</u>



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1635 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	61 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	547409414XB

CarCheck.co.uk page 12/12