



RENAULT

SM56EHE

report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE 16V EU4
Colour	Blue
Year of manufacture	2007
Top speed	114 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	127 Nm at 3.750 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.9 mpg
CO2 emission	165 g/km
CO2 label	G





MOT history

MOT expiry date	2025-01-21
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	77
Total items failed	43

MOT #25	2024-01-22 15:26
---------	------------------

MOT test number	801483991094
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-21
------------------	------------

- Advice

Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Minor

Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice

Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice

Oil leak, but not excessive engine oil unable to fully inspect due to engine cover/undertray fitted (8.4.1 (a) (i))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Advice

Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice

Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice

Offside Brake pipe corroded, covered in grease or other material front to rear corroded at front section (1.1.11 (c))
- Advice

Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice

Suspension component corroded but not seriously weakened rear axle corroded (5.3.3 (b) (i))

**MOT #24**

2024-01-22 15:26

MOT test number

530674271784

Result**✗ Failed**

- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Oil leak, but not excessive engine oil unable to fully inspect due to engine cover/undertray fitted (8.4.1 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect no image (4.1.2 (c))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear corroded at front section (1.1.11 (c))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Suspension component corroded but not seriously weakened rear axle corroded (5.3.3 (b) (i))

**MOT #23**

2023-10-17 11:14

MOT test number

800894264689

Result**✗ Failed**

- Advice** Brake hose has slight corrosion to ferrule ALL FLEXI HOSES (1.1.12 (f) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material TO CALIPER (1.1.11 (c))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Front Brakes imbalanced across an axle by more than 50% Axle 1 (1.2.1 (b) (ii))
- Fail** Brake pedal has insufficient reserve travel (1.1.2 (a))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Fail** Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material FRONT TO REAR (1.1.11 (c))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Brake fluid significantly below minimum mark (1.1.10 (d) (ii))
- Fail** Oil leaking excessively from engine (8.4.1 (a) (i))
- Fail** Nearside Rear Hydraulic brake calliper insecurely mounted (1.1.16 (c) (i))
- Advice** Rear axle is corroded
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))

**MOT #22**

2022-10-11 21:15

MOT test number

610227863142

Result

✓ Passed

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Car only just met emission requirements after several attempts co / hydrocarbons
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Upper strut bearing / slight noise
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #21

2021-09-28 12:53

MOT test number

867459447004

Result

✓ Passed

- Minor** Parking brake lever ratchet mechanism obviously worn (1.1.6 (b) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))
- Advice** Front bumper and lower plastic panels loose
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**MOT #20**

2021-09-23 20:37

MOT test number

906135221364

Result**✗ Failed****Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Front bumper and lower plastic panels loose**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Rear Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))**Advice** Heat shield above catalyser insecure**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Rear Registration plate inscription illegible (0.1 (b))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Minor** Parking brake lever ratchet mechanism obviously worn (1.1.6 (b) (i))

**MOT #19**

2021-08-26 10:33

MOT test number

783062009371

Result**✗ Failed**

- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))
- Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))
- Fail** Offside Front Brake pipe excessively corroded to rear (1.1.11 (c))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Rear Brake pipe excessively corroded across axle (1.1.11 (c))
- Fail** Windscreen washer not working (3.5 (a))
- Fail** Rear Exhaust system insecure (6.1.2 (a))

**MOT #18** 2020-09-01 12:13**MOT test number** 256176128868**Result** ✓ Passed**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #17** 2019-09-04 10:10**MOT test number** 730920262571**Result** ✓ Passed**MOT #16** 2019-09-04 10:10**MOT test number** 217030970726**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #15** 2018-09-07 08:23**MOT test number** 326451562349**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2018-09-07 08:23**MOT test number** 443292013983**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Headlamp aim too high and too far to the right. (4.1.2 (a))

MOT #13 2017-09-08 12:35**MOT test number** 315738833887**Result** ✓ Passed

**MOT #12**

2017-04-04 10:27

MOT test number

834708017783

Result

✓ Passed

- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #11

2016-04-05 14:21

MOT test number

321790993205

Result

✓ Passed

MOT #10

2016-04-04 11:54

MOT test number

505523974462

Result

✗ Failed

- Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)

MOT #9

2016-02-11 09:43

MOT test number

370834959950

Result

✓ Passed

**MOT #8** 2015-02-20 16:09**MOT test number** 935331155018**Result** ✓ Passed**MOT #7** 2015-02-20 09:10**MOT test number** 927041255045**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Notice** Offside steering rack end**MOT #6** 2014-02-13 09:16**MOT test number** 375264144022**Result** ✓ Passed**Notice** Nearside steering rack end worn**MOT #5** 2013-02-08 15:50**MOT test number** 926499433041**Result** ✓ Passed**MOT #4** 2013-02-08 09:00**MOT test number** 909379133057**Result** ✗ Failed**Fail** Rear brake disc in such a condition that it is seriously weakened (3.5.1i)



MOT #3	2012-02-17 11:56
MOT test number	387288742056
Result	✓ Passed
Notice	Rear discs corroded
Notice	Both rack ends slight play
Notice	Front discs pitted

MOT #2	2011-02-14 14:18
MOT test number	845395541004
Result	✓ Passed

MOT #1	2010-02-16 13:29
MOT test number	961927940087
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
21 January 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	SM56EHE
Plate since	2019-03-28
Current registration	SM56EHE
Plate since	2019-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-02-27
Last registration	2024-01-22
Complete history	See info



Registration #1	2007-02-27	22 mi
Registration #2	2010-02-16	32.907 mi
Registration #3	2011-02-14	41.337 mi
Registration #4	2012-02-17	48.296 mi
Registration #5	2013-02-08	55.710 mi
Registration #6	2013-02-08	55.710 mi
Registration #7	2014-02-13	62.981 mi
Registration #8	2015-02-20	70.025 mi
Registration #9	2015-02-20	70.025 mi
Registration #10	2016-02-11	79.949 mi
Registration #11	2016-04-04	80.275 mi
Registration #12	2016-04-05	80.280 mi
Registration #13	2017-04-04	89.554 mi
Registration #14	2018-04-04	98.828 mi
Registration #15	2019-04-04	108.102 mi
Registration #16	2020-04-04	117.376 mi
Registration #17	2021-04-04	126.650 mi
Registration #18	2022-04-04	135.924 mi
Registration #19	2023-04-04	145.198 mi
Registration #20	2024-01-22	154.472 mi
Registration #21	2024-01-22	154.472 mi
Registration #22	2024-01-22	154.472 mi
Registration #23	2024-01-22	154.472 mi
Registration #24	2024-01-22	154.472 mi
Registration #25	2024-01-22	154.472 mi
Registration #26	2024-01-22	154.472 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1458 mm
Length	4209 mm
Wheel base	2625 mm
Kerb weight	1165 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D018005