





report date: 2024-03-28

#### General information

Make	MAZDA
Model	5 D SPORT VENTURE EDITION
Colour	White
Year of manufacture	2014
Top speed	111 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/12



### Internet history

#### Entry 1

Date 2022-04-15

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-30
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	22
Total items failed	4

MOT #9		2023-09-27 12:33
MOT test	number	217373708424
Result		✓ Passed
Next expi	ry date	2024-09-30
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice	Fuel filler neck corroded	

MOT #8	2023-09-27 08:36
MOT test number	709497181909
Result	<b>×</b> Failed
Advice Nearside Front Inner Tyre worn clo	se to legal limit/worn on edge (5.2.3 (e))
Advice Fuel filler neck corroded	
Fail Rear Brake disc significantly and obvious	ously worn (1.1.14 (a) (i))
Advice Front Brake disc worn, pitted or sco	ored, but not seriously weakened (1.1.14 (a) (ii))
Fail Nearside Front Anti-roll bar ball joint e	xcessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 3/12



MOT #7

MOT test number

114120953840

Result

✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT test number

Result

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

Advice Under trays fitted

 MOT #5
 2021-09-30 12:06

 MOT test number
 341218271041

Result X Failed

Advice Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

**Advice** Under trays fitted

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement marked in yellow (5.3.4 (a) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Lower Suspension arm ball joint excessively worn marked in yellow (5.3.4 (a) (i))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



**MOT #4** 2020-09-28 12:41

**MOT test number** 701658821992

**Result** ✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))

**Advice** Rear Brake lining(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2019-03-29 15:21

**MOT test number** 572354569583

**Result** ✓ Passed

MOT #2 2018-03-26 08:47

MOT test number 464217674131

**Result** 
✓ Passed

**Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Inner Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2017-03-31 09:30

**MOT test number** 471554658618

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 May
Days left	368
MOT expiry date	30 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



### Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	
manage of the same	
***************************************	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	UK ZIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-26
Last registration	2023-09-27
Complete history	See info



Registration #1	2014-03-26	22 mi
Registration #2	2017-03-31	26.581 mi
Registration #3	2018-03-26	36.598 mi
Registration #4	2019-03-29	45.594 mi
Registration #5	2020-09-28	58.183 mi
Registration #6	2021-09-30	67.007 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 11/12



### Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1750 mm
Height	1615 mm
Length	4585 mm
Wheel base	2750 mm
Kerb weight	1490 kg
Max. allowed weight	2125 kg

### Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	Y6 359565

CarCheck.co.uk page 12/12