




report date: 2024-03-28

General information

Make	FORD
Model	FUSION FUSION +
Colour	Grey
Year of manufacture	2008
Top speed	109 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	146 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	181 g/km
CO2 label	I





Internet history

Entry 2


Date	2021-11-09
Pictures	7
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

Entry 1

Date	2021-11-08
Pictures	7
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://autotrader.co.uk)



## MOT history

MOT expiry date	2024-11-15
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	28
Total items failed	12

MOT #19	2023-11-13 14:38
MOT test number	824135633665
Result	✓ Passed
Next expiry date	2024-11-15
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #18	2022-11-14 13:00
MOT test number	932103148160
Result	✓ Passed

MOT #17	2022-11-14 13:00
MOT test number	624779516326
Result	✗ Failed
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #16	2021-11-16 11:36
MOT test number	253591773426
Result	✓ Passed

**MOT #15**

2021-11-15 14:05

**MOT test number**

242480486280

**Result****✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #14**

2021-01-13 17:02

**MOT test number**

929892059030

**Result****✓ Passed****Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #13**

2021-01-13 09:51

**MOT test number**

282990948955

**Result****✗ Failed****Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #12** 2019-07-19 10:20**MOT test number** 781228906571**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides of car (1.1.14 (a) (ii))**Advice** Nearside rear tyre worn close to limit.**Advice** Offside Rear Wheel bearing slightly noisy and slight play (5.1.3 (b) (i))**Advice** Both front tyres starting to perish and wear on outer shoulders of tread.**MOT #11** 2018-07-02 10:25**MOT test number** 981612405060**Result** ✓ Passed**Advice** Nearside HEAD LAMP AIM ON THE LOW LIMIT**MOT #10** 2018-07-02 10:25**MOT test number** 285177899839**Result** ✗ Failed**Pass with rectification** Windscreen washer not working (3.5 (a))**Advice** Nearside HEAD LAMP AIM ON THE LOW LIMIT**MOT #9** 2017-07-04 14:35**MOT test number** 979969343838**Result** ✓ Passed**Advice** Slight play in offside rear wheel bearing**MOT #8** 2016-06-13 08:48**MOT test number** 299658823046**Result** ✓ Passed**Advice** SILL COVERS FITTED

**MOT #7** 2015-06-30 14:23**MOT test number** 266971085154**Result** ✓ Passed

- Notice** Nearside front and rear tyres perished slightly
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Items removed from driver's view prior to test
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)
- Notice** Both front wiper blades split but clear screen effectively

**MOT #6** 2015-06-29 12:41**MOT test number** 148890685182**Result** ✗ Failed

- Advice** Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)
- Notice** Both front wiper blades split but clear screen effectively
- Fail** Nearside Rear Seat belt has a cut which has significantly weakened the webbing (5.2.2a)
- Notice** Nearside front and rear tyres perished slightly
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Items removed from driver's view prior to test
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #5** 2014-06-04 14:48**MOT test number** 228885354139**Result** ✓ Passed

- Notice** Sill covers fitted



MOT #4	2014-06-04 14:48
MOT test number	239955054198
Result	✗ Failed
Notice	Sill covers fitted
Pass with rectification	Nearside Stop lamp not working (1.2.1b)

MOT #3	2013-07-01 13:33
MOT test number	366912883161
Result	✓ Passed

MOT #2	2012-11-02 10:44
MOT test number	868057402318
Result	✓ Passed

MOT #1	2011-09-19 09:38
MOT test number	626652161287
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
15 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	15 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-






Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EK58GSV
Plate since	2019-03-28
Current registration	EK58GSV
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-10-27
Last registration	2023-11-13
Complete history	<a href="#">See info</a>



Registration #1	2008-10-27	24 mi
Registration #2	2011-09-19	31.158 mi
Registration #3	2012-11-02	35.838 mi
Registration #4	2013-07-01	38.080 mi
Registration #5	2014-06-04	42.310 mi
Registration #6	2015-06-29	46.538 mi
Registration #7	2015-06-30	46.538 mi
Registration #8	2016-06-13	49.490 mi
Registration #9	2017-07-04	57.680 mi
Registration #10	2018-07-02	64.409 mi
Registration #11	2018-07-02	64.409 mi
Registration #12	2019-06-29	71.277 mi
Registration #13	2019-06-29	71.277 mi
Registration #14	2019-06-29	71.277 mi
Registration #15	2019-06-29	71.277 mi
Registration #16	2019-06-29	71.277 mi
Registration #17	2019-06-29	71.277 mi
Registration #18	2019-06-29	71.277 mi
Registration #19	2019-06-29	71.277 mi
Registration #20	2019-06-29	71.277 mi
Registration #21	2019-06-29	71.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	8L72094