





report date: 2024-03-28

General information

| Make | BMW |
|---------------------|-----------------------------|
| Model | 218 218D LUXURY GRAN TOURER |
| Colour | Black |
| Year of manufacture | 2016 |
| Top speed | 127 mph |
| 0 - 60 mph | 9.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 150 BHP |
|-------------------------|---------------------|
| Max. torque | 330 Nm at 1.750 rpm |
| Engine capacity | 1.995 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 55.4 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 115 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-06-15

Pictures 9

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



| MC | TC | history | |
|----|----|---------|--|
|----|----|---------|--|

| MOT expiry date | 2025-02-21 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 6 |
| Failed MOT tests | 0 |
| Total advice items | 7 |
| Total items failed | 0 |

| MOT #6 | 2024-02-22 16:10 |
|------------------|------------------|
| MOT test number | 227527375297 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-21 |

| MOT #5 | | 2023-08-14 09:25 |
|----------|--|------------------|
| MOT test | number | 374577389887 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #4 | 2022-07-29 12:52 |
|-----------------|------------------|
| MOT test number | 254681358024 |
| Result | ✓ Passed |

| MOT #3 | 2021-08-04 14:55 |
|-----------------|------------------|
| MOT test number | 517182812359 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



MOT test number

S37434022185

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1

MOT test number

Result

Advice Nearside Front Windscreen damaged (stone chip), not adversely affecting driver's view

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 279 |
| MOT expiry date | 21 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| e union matery | |
|---|-------------|
| For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report | |
| | |
| *************************************** | |
| | |
| | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this BMW had different number plates. | |
| Number of plates | , |
| Current registration | NE NE |
| Plate since | |
| Current registration | NE NE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2016-09-14 |
| Last registration | 2024-02-22 |
| Complete history | See info |



| Registration #1 | 2016-09-14 | 19 mi |
|-----------------|------------|-----------|
| Registration #2 | 2019-08-31 | 30.296 mi |
| Registration #3 | 2020-09-08 | 41.897 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 71.777 es |

More info >

CarCheck.co.uk page 10/11




Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| 50501 | |
| S0566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 91% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 86% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 2038 mm |
|---------------------|---------|
| Height | 1612 mm |
| Length | 4556 mm |
| Wheel base | 2780 mm |
| Kerb weight | 1500 kg |
| Max. allowed weight | 2180 kg |

Additional information

| Fuel tank capacity | 51 l |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 11/1 |