



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI
Colour	Black
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-26
Pictures	5
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



## MOT history

MOT expiry date	2024-10-18
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	22
Total items failed	9

MOT #16	2023-10-15 15:42
MOT test number	824229451676
Result	✓ Passed
Next expiry date	2024-10-18
<b>Minor</b>	Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt both sides (2.1.3 (g) (i))
<b>Advice</b>	Front Outer Suspension arm pin or bush worn but not resulting in excessive movement rear both sides (5.3.4 (a) (i))
<b>Minor</b>	Front Suspension arm ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))

MOT #15	2023-10-15 15:42
MOT test number	331682731277
Result	✗ Failed
<b>Minor</b>	Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt both sides (2.1.3 (g) (i))
<b>Pass with rectification</b>	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
<b>Minor</b>	Front Suspension arm ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))
<b>Advice</b>	Front Outer Suspension arm pin or bush worn but not resulting in excessive movement rear both sides (5.3.4 (a) (i))
<b>Pass with rectification</b>	Nearside Front Seat belt installation anchorage insecure (10.1 (d))

**MOT #14** 2022-10-19 08:44**MOT test number** 746744469739**Result** ✓ Passed

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement o/s & n/s (5.3.4 (a) (i))

**MOT #13** 2021-10-18 12:57**MOT test number** 300779739470**Result** ✓ Passed**MOT #12** 2021-05-01 13:23**MOT test number** 377486085071**Result** ✓ Passed**MOT #11** 2020-05-11 08:43**MOT test number** 157784753832**Result** ✓ Passed

**Advice** Rear Tyre slightly damaged/cracking or perishing Both Sides (5.2.3 (d) (ii))

**MOT #10** 2020-05-04 11:51**MOT test number** 366366544539**Result** ✗ Failed

**Advice** Rear Tyre slightly damaged/cracking or perishing Both Sides (5.2.3 (d) (ii))

**Fail** Nearside Front Tyre has had the tread recut (5.2.3 (g))

**MOT #9** 2019-06-14 10:09**MOT test number** 128185571192**Result** ✓ Passed

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2018-06-26 12:45**MOT test number** 932294271821**Result** ✓ Passed**MOT #7** 2017-06-26 13:44**MOT test number** 357371959269**Result** ✓ Passed**MOT #6** 2017-06-26 10:15**MOT test number** 121190680985**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Nearside rear tyre heavily perished**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #5** 2016-06-16 10:57**MOT test number** 474002306158**Result** ✓ Passed**Advice** Offside rear tyre heavily perished**Advice** Nearside rear tyre heavily perished**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2016-06-16 09:34**MOT test number** 671369309022**Result** ✗ Failed**Advice** Offside rear tyre heavily perished**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside rear tyre heavily perished**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2015-06-17 12:01**MOT test number** 378108765104**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-07-02 14:43**MOT test number** 748323484157**Result** ✓ Passed**Notice** Both rear tyres cracking**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2014-07-02 13:34**MOT test number** 638053584110**Result** ✗ Failed**Notice** Both rear tyres cracking**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
18 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	18 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>FR11UWL</b>
Plate since	2019-03-29
Current registration	 <b>FR11UWL</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-08-25
Last registration	2023-10-15
Complete history	<a href="#">See info</a>



Registration #1	2011-08-25	21 mi
Registration #2	2014-07-02	32.449 mi
Registration #3	2014-07-02	32.454 mi
Registration #4	2015-06-17	36.506 mi
Registration #5	2016-06-16	43.910 mi
Registration #6	2016-06-16	43.910 mi
Registration #7	2017-06-26	53.030 mi
Registration #8	2017-06-26	53.030 mi
Registration #9	2018-06-26	60.158 mi
Registration #10	2019-06-26	66.287 mi
Registration #11	2019-06-26	66.287 mi
Registration #12	2019-06-26	66.287 mi
Registration #13	2019-06-26	66.287 mi
Registration #14	2019-06-26	66.287 mi
Registration #15	2019-06-26	66.287 mi
Registration #16	2019-06-26	66.287 mi
Registration #17	2019-06-26	66.287 mi
Registration #18	2019-06-26	66.287 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Number of axles**

2

**Engine number**

CAY 586764