



**AV06HXXH**

report date: 2024-03-28

General information

Make	SUZUKI
Model	ALTO GL
Colour	Silver
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	85 Nm at 3.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg



**MOT history**

<b>MOT #16</b>	2020-09-18 13:18
<b>MOT test number</b>	801708774413
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-09-17
<b>Advice</b>	Rear Exhaust mounting defective (6.1.2 (a))
<b>Advice</b>	Exhaust in a rusty condition
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
<b>Advice</b>	Rear Brake pipes rusty

<b>MOT #15</b>	2020-09-17 15:55
<b>MOT test number</b>	645202978072
<b>Result</b>	✗ Failed
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
<b>Fail</b>	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
<b>Fail</b>	Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
<b>Advice</b>	Rear Exhaust mounting defective (6.1.2 (a))
<b>Advice</b>	Rear Brake pipes rusty
<b>Fail</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Fail</b>	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
<b>Advice</b>	Exhaust in a rusty condition

<b>MOT #14</b>	2019-08-07 07:13
<b>MOT test number</b>	202513054107
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Exhaust front pipe & rear box corroding
<b>Advice</b>	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #13** 2019-08-05 08:23**MOT test number** 687382519027**Result** ✗ Failed**Fail** Nearside Rear Position lamp showing white light to the rear (4.2.3 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Rear Position lamp lens seriously defective sharp edges (4.2.1 (b))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Exhaust front pipe & rear box corroding**MOT #12** 2018-08-03 08:14**MOT test number** 203084538917**Result** ✓ Passed**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**MOT #11** 2017-07-31 13:21**MOT test number** 638459954764**Result** ✓ Passed**Advice** Rear exhaust silencer deteriorated**MOT #10** 2017-07-31 09:34**MOT test number** 268212083356**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear exhaust silencer deteriorated**MOT #9** 2016-07-20 11:44**MOT test number** 455056901793**Result** ✓ Passed

**MOT #8** 2016-07-16 08:38**MOT test number** 624220133128**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Rear Exhaust system not adequately supported (7.1.1)**MOT #7** 2015-07-25 11:25**MOT test number** 369656905203**Result** ✓ Passed**Notice** COIL SPRINGS AND ARMS RUSTED**MOT #6** 2014-07-21 10:54**MOT test number** 799062804254**Result** ✓ Passed**MOT #5** 2013-08-01 10:12**MOT test number** 658023513254**Result** ✓ Passed**MOT #4** 2012-06-25 10:09**MOT test number** 876517372109**Result** ✓ Passed**MOT #3** 2011-06-14 11:45**MOT test number** 458385361179**Result** ✓ Passed**MOT #2** 2010-05-28 10:28**MOT test number** 102078140120**Result** ✓ Passed



MOT #1	2009-05-13 13:14
MOT test number	681233539103
Result	✓ Passed



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	AV06HXH
Plate since	2019-09-28
Current registration	AV06HXH
Plate since	2019-09-28

More info >





Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-03-21
Last registration	2020-09-18
Complete history	<a href="#">See info</a>



Registration #1	2006-03-21	14 mi
Registration #2	2009-05-13	8.558 mi
Registration #3	2010-05-28	10.139 mi
Registration #4	2011-06-14	11.156 mi
Registration #5	2012-06-25	12.141 mi
Registration #6	2013-08-01	13.013 mi
Registration #7	2014-07-21	24.523 mi
Registration #8	2015-07-25	32.068 mi
Registration #9	2016-07-16	37.965 mi
Registration #10	2016-09-20	38.377 mi
Registration #11	2016-10-20	38.377 mi
Registration #12	2016-11-20	38.377 mi
Registration #13	2016-12-20	38.377 mi
Registration #14	2017-01-20	38.377 mi
Registration #15	2017-02-20	38.377 mi
Registration #16	2017-03-20	38.377 mi
Registration #17	2017-04-20	38.377 mi

More info >



Dimensions & weight

Width	1495 mm
Height	1405 mm
Length	3495 mm
Wheel base	2360 mm
Kerb weight	805 kg
Max. allowed weight	1165 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	F10DN 3208347