





report date: 2024-03-28

#### General information

Make	FIAT
Model	PANDA POP
Colour	Turquoise
Year of manufacture	2012
Top speed	102 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/12



VK62UXY

report date: 2024-03-28

## Internet history

#### Entry 8

Date 2023-03-27

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 7


Date 2023-01-05

Pictures 20

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 6

Date 2021-12-22

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk


#### Entry 5

Pictures 9

## Listing price <u>View report</u>









source: autotrader.co.uk

Entry 4

Date	2021-09-14

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3

Date 2021-09-14	
-----------------	--

Pictures 9

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 2

Date	2021-08-09
Pictures	9
Listing price	View report










source: autotrader.co.uk

Entry 1

Date	2021-06-13
Pictures	9
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-07
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	7
Total items failed	9

MOT #13	2023-11-13 15:33
MOT test number	564749479546
Result	✓ Passed
Next expiry date	2024-12-07

MOT #12	2022-12-01 11:08
MOT test number	900507068979
Result	<b>√</b> Passed

MOT #11	2021-11-27 10:	44
MOT test	number 9321145901	98
Result	✓ Passo	ed
Advice	Engine oil sump is corroded	
Advice	Rear Suspension component corroded but not seriously weakened axle (5.3.3 (b) (i))	

CarCheck.co.uk page 3/12



Fail

VK62UXY report date: 2024-03-28

**MOT #10** 2021-11-20 13:39

MOT test number 494658766807

**Result** X Failed

**Advice** Engine oil sump is corroded

Advice Rear Suspension component corroded but not seriously weakened axle (5.3.3 (b) (i))

**Fail** Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords edge (5.2.3 (d) (i))

Advice Front Inner Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))

MOT #9 2020-12-08 15:34

**MOT test number** 336990772374

Result \sqrt{Passed}

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #8** 2020-12-07 12:00

**MOT test number** 741213305895

**Result** X Failed

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Rear Brake cable damaged (1.1.15 (a))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #7 2019-12-07 09:38

**MOT test number** 286712609171

**Result** ✓ Passed

MOT #6 2018-09-27 08:48

**MOT test number** 163186973349

CarCheck.co.uk page 4/12



Result

VK62UXY
report date: 2024-03-28

× Failed

MOT #5 2018-09-24 11:11

MOT test number 785843472101

Result X Failed

Fail Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail** Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

**MOT #4** 2017-09-18 08:31

**MOT test number** 666231214047

**Result** ✓ Passed

MOT #3 2017-09-18 08:31

**MOT test number** 564367456530

**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2016-09-17 10:15

MOT test number 655577796250

Result 

Passed

MOT #1 2015-09-22 10:38

**MOT test number** 510005144628

**Result** 
✓ Passed

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 May
Days left	3
MOT expiry date	7 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK CONTRACTOR
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2012-09-28
Last registration	2023-11-13
Complete history	See info



Registration #1	2012-09-28	27 mi
Registration #2	2015-09-22	12.342 mi
Registration #3	2016-09-17	20.671 mi
Registration #4	2017-09-18	33.290 mi
Registration #5	2017-09-18	33.290 mi
Registration #6	2018-09-24	43.982 mi
Registration #7	2018-09-27	44.034 mi
Registration #8	2019-12-07	61.872 mi
Registration #9	2020-12-07	76.145 mi
Registration #10	2020-12-08	76.150 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 esi
Registration #16		11.777 es
Registration #17		91.777 esi
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



## Dimensions & weight

Width	1882 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg

# Additional information

Fuel tank capacity	37 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12